

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR
P. O. Box 3249, Englewood, Co. 80155 OIL CON. DIV.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)
See also space 17 below.)
At surface

1100' FNL, 800' FEL

14. PERMIT NO.
30-045-25805

15. ELEVATIONS (Show whether by, or, or, etc.)

12. COUNTY OR PARISH	13. STATE
San Juan	NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASINO
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) Progress

**REPAIRING WELL
ALTERING CASING
ABANDONMENT®**

(Other) Progress report
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sonar pertinent to this work.) *

2/2/85 MIRURT. Spud well @ 6 pm 2-2-85. Drill to 302 circ, RU & ran 7 jts 288' 9 5/8
36# K-55 STC csg, set @301. Cmt w/250 sx (295 CF) CL-B +2% CaCl2 + 1/4#/sx celloseal.
Good circ. Circ 10 bbls cmt. PD 12:45 am 2-3-85.

2/3/85 NU, test blind rams to 1000 psi, 30 min, OK. Attempt to test pipe rams, BS circ w/200 psi. RIH tag plug @294'. Set dn 30,000#, attempt to pmp off, no success. POOH. WOC. Test csg to 300 psi, 3 min OK. WOC. Close blind rams to 800 psi, 15 min OK. RIH, attempt to test pipe rams, circ BS. Drill out plug, very green cmt to 301'. Circ. POOH, NU companion flange & cmt head WO cmtrs.

2/4/85 Pmp 180 sx (212CF) CL-8 + 3% CaCl2 + 3% Calseal displace plug to 260'. Good
circ thru out job, circ 23 bbls exc cmt. cmt in place @9:30 am 2-4-85. WOC. NUBOPE,
PT 1000# 30 min OK. Drill plug & hard cmt. Drill ahead to 1228.

2/7/85 Ran 70 jts 7" 23# K-55 STC csg set @3002, FC @2942, DV @1340. CMT 1st stage w/75 sx (138CF) lite + 100 sx (118CF) CL-B + 2% CaCl₂ + 1/4#/sx celloseal. PD @10:30 am, open DV, circ. cmt 2nd stage w/145 sx (266CF) lite, tail w/75 sx (88CF) CL-B + 2% CaCl₂, pd @3 PM 2-7. WOC. PT BOPE, ran temp survey, TOC @300. Drill out, unload hole w/N2. Attempt to dry up hole.

18. I hereby certify that the foregoing is true and correct

SIGNED Shelley H. H. - [Signature]

TITLE Sr. Regulatory Analyst **DATE** 2/14/85

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

FEB 21 1955

***See Instructions on Reverse Side**

FARMINGTON RESOURCE AREA

BY

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.