

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-10J
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 60, Artesia, NM 88210

DISTRICT III
1000 Rio Brator Rd., Alamo, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-045-25944
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Martinez Gas Com I
8. Well No.	#1A
9. Pool name or Wildcat	Blanco Mesaverde
10. Elevation (Show whether OF, RKB, RT, GR, etc.)	5544' KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
Amoco Production Company Attn: John Hampton

3. Address of Operator
P.O. Box 800, Denver, Colorado 80201

4. Well Location
Unit Letter 0 : 790 Feet From The South Line and 1450 Feet From The East Line
Section 24 Township 29N Range 10W NM 117-1 San Juan County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: Bradenhead Repair ☒	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attachment for procedures.

RECEIVED
SEP 18 1992
OIL CON. DIV
DIST. 3

If you have any questions, please contact Julie Acevedo (303) 830-6003.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Hampton / DUT TITLE Sr. Staff Admin. Supv. DATE 9/15/92

TYPE OR PRINT NAME John Hampton TEL EXTENSION NO.

(This space for State Use)

APPROVED BY Original Signed by CHARLES GHOLSON TITLE DEPUTY OIL & GAS INSPECTOR DIST. 3 DATE SEP 18 1992

COORDINATOR OF APPROVAL, IF ANY:

Martinez Gas Com /I/ #1A
4/16/92 - 4/25/92

MIRUSU. Kill well. NDWH & NUBOPS. PR TST BOPS to 2000psi. OK. PU single & tag fill 4236'. PU 1 single. TOH. TIH w/ scraper. TOH. TIH w/ plug. Set plug @ 3727'. PR TST CSG to 150psi. OK. Dump sand on plug. TOH. RI WLE. Run CBL-VDL-GR-CCL log from 2850' to surf. TIH w/ perf gun. Shoot 2 holes @ 1400'. RD WLE. Make up PKR. TIH & set at 874'. PMP 5 BBLS dye WTR ahead of CMT. PMP 140 BBLS oilwell + 2% CACL2. Obtain dye wtr rtns. Lost circ. Go to displacement. Rel PKR. TOH & lay dwn PKR. Make up bit on collars. TIH on 2-3/8 TBG. Tag CMT to 956'. RU swivel. Break circ. DRL CMT to 1274'. RU swivel & break circ. DRL CMT to 1414'. Circ hole clean. Lay dwn swivel. PR TST CSG to 500psi. Ok. PR TST BR.HD to 500psi. TOH w/ TBG collars. RI WLE. Run CBL-VDL-GR-CCL log from 400-surf. Bond. RD WLE. TIH w/ collars. TIH w/ ret. hd. Circ sand off plug. Rel. PU to 1425'. Set plug & TOH. PU scraper & run to 1400'. TOH. TIH w/ ret. hd. Latch onto plug. TOH w/ plug. Make up bailer & TIH. Tag fill @ 4226'. Bail 2'. Rotate & work bailer. TOH. Kill well. Make up bit on 4 drl collars & TIH. Tag fill 4226'. RU swivel. ST PMP N2. TOH w/ TBG & collars. Lay dwn collars. Run prod TBG. 2 3/8" TBG landed @ 4226.64. NDBOPS. NUWH. Swab. Well flowing. RDMOSU.