
bp



BP America, Inc. 501 WestLake Park Blvd. Houston, TX 77079-3092

Phone: 281-366-2000



March 11, 2002

Dorothy,

On Feb 6^{th} there was a CIBP set @ 5900'. That bridge plug remains in the well separating the DK perforations from the Chacra. This well is not currently commingled.

Please accept this as answer to your question of why the tubing is set at 2597.64' and approve our C-103 and C-104.

Sincerely,

Cherry Hlava

Cherry Hlava

So To Appropriate District Office	State of New Mexico		Form C-103
District !	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		30-045-26125
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			The results of the regreement wante.
PROPOSALS.)	SATION FOR PERMIT" (FORM C-101) FO	Gallegos Canyon Unit Com A	
1. Type of Well:			a magaz a anyan ann adni A
Oil Well Gas Well	Other		
2. Name of Operator		8. Well No.	
BP America Production Company	Attn: Cherry Hlava		
3. Address of Operator	, State of the sta		9. Pool name or Wildcat
P.O. Box 3092 Houston, TX	77253		Otero Chacra
4. Well Location			Otero Chacra
Unit Letter 6 1850 feet from the North line and 1475 feet from the East line			
and and <u>rivo</u> leet nom the <u>East</u> time			
Section 25	Township 29N Range	12W	NMPM San Juan County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
5491'			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
DEDECOM DEMEDIAL MODIC CO.		REMEDIAL WORK	
		THE WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL			LING OPNS. PLUG AND
PULL OF ALTER CASING	MU 710	ABANDONMENT	
PULL OR ALTER CASING	CASING TEST AND		
COMPLETION CEMENT JOB			
OTHER: Complete			Otero Chacra & DHC
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompilation.			
BP America completed subject well into the Chacra formation & DHC with the Dakota as follows:			
01/29/02 RUSU & take readings; tbg 230 psi, csg 190 psi, BH 0 psi. Blw well dn. NDWH & NUBOP. SWFN.			
01/30/02 Tbg 7 psi, csg 0 psi. RU wireline & fish tbg. Cut off pipe @ 5510'. RD wireline. SDFN.			
01/31/02 TOH w/tbg & spot air pkg, PU wash pipe, TIH & TOH w/tbg, TIH to top of fish & run pwr swivel. SDFN.			
or recompilation. BP America completed subject well into the Chacra formation & DHC with the Dakota as follows: 01/29/02 RUSU & take readings; tbg 230 psi, csg 190 psi, BH 0 psi. Blw well dn. NDWH & NUBOP. SWFN. 01/30/02 Tbg 7 psi, csg 0 psi. RU wireline & fish tbg. Cut off pipe @ 5510'. RD wireline. SDFN. 01/31/02 TOH w/tbg & spot air pkg, PU wash pipe, TIH & TOH w/tbg, TIH to top of fish & run pwr swivel. SDFN. 02/01/02 Take readings & blw dn well. Tag & wash over fish. TIH w/overshot, latch onto fish. TOH w/fish. LD overshot. SDFN.			
02/05/02 Train Golden Rules of Safety. Set CIBPO 5900'			
02/06/02 Take Readings. Review Golden Rules & safety policies. Ran CBL/GR/CCL logs. SDFN.			
02/07/02 RUSU. TIH w/3.125" gun & perf Chacra formation from 2516' – 2650' w/1 JSPF total of 72 shots. SDFN.			
02/08/02 MIRU & frac Chacra formation w/500 gal 15% HCL acid, followed w/ 111,708# 16/30 Brady Snd; pmp 70% nitrogen foam			
1/30/02 To psi, csg 0 psi. RU wireline & fish tbg. Cut off pipe @ 5510'. RD wireline. SDFN. 1/31/02 TOH w/tbg & spot air pkg, PU wash pipe, TIH & TOH w/tbg, TIH to top of fish & run pwr swivel. SDFN. 1/31/02 Take readings & blw dn well. Tag & wash over fish. TIH w/overshot, latch onto fish. TOH w/fish. LD overshot. SDFN. 1/31/02 Take readings. Review Golden Rules & safety policies. Ran CBL/GR/CCL logs. SDFN. 1/31/04 RUSU. TIH w/3.125" gun & perf Chacra formation from 2516' - 2650' w/1 JSPF total of 72 shots. SDFN. 1/31/04 RISU. TiH w/3.125" gun & perf Chacra formation from 2516' - 2650' w/1 JSPF total of 72 shots. SDFN. 1/31/04 RISU. TiH w/3.125" gun & perf Chacra formation w/500 gal 15% HCL acid, followed w/ 111,708# 16/30 Brady Snd; pmp 70% nitrogen foam 1/31/02 Take readings. Repair flw line leak. Making water & frac. SDFN. 1/31/02 Take readings. Csr 820 psi. Pmp'd 45 block will all TIM. TIM. TIM. TIM. TIM. TIM. TIM. TIM.			
1 and readings. Cog 620 DSI. Filli) (14) DIS TO KIII Well THE W/DRD & 75 stands Cot when TOTA THAT 6			
well wiss dis. Foll wiplug. Tiff wiplu	duction string Pressure tet the to soon a	ci hold ak TILL	1 - C
oziloioz Take readings. Csg 620 psi. K	U flw line. Blw DN, well never died. T	TH & landed the @259	97.64 RU B&R slick line & fish out tbg plug.
RDSU move off location.	441A2	(======================================	No Best sheet the & fish out tog plug.
I hereby certify that the information	above is true and complete to the L	-1 6 1	
I hereby certify that the information	above is true and complete to the b	est of my knowledge	e and belief.
SIGNATURE Cherry Have	TITLE R	anulatoma Amelicia	DATE:
		egulatory Analyst	DATE <u>02/20/2002</u>
Type or print name Cherry Hlava Telephone No. 281-366-4081			
(This space for State use)			
APPPROVED BY TITLE DATE			
Conditions of approval, if any:			
	1		