

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DC, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Altec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-045-26181
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	7. Lease Name or Unit Agreement Name Gallegos Canyon Unit
2. Name of Operator Amoco Production Company Attn: John Hampton	8. Well No. # 109E
3. Address of Operator P.O. Box 800, Denver, Colorado 80201	9. Pool name or Wildcat Basin Dakota
4. Well Location Unit Letter <u>E</u> : <u>1675</u> Feet From The <u>North</u> Line and <u>850</u> Feet From The <u>West</u> Line Section <u>18</u> Township <u>29N</u> Range <u>12W</u> <u>N.M.</u> San Juan County	
10. Elevation (Show whether DF, RXD, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPS. ☐
OTHER: <u>Bradenhead Repair</u> ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: <u>BRADENHEAD Repair</u> ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Please see attachment for procedures.

RECEIVED
JUN 19 1992
OIL CON. DIV
DIST. 3

Please contact Julie Acevedo (303) 830-6003., if you have any questions.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE <u>John Hampton</u>	TITLE <u>Sr. Staff Admin. Supv.</u> DATE <u>6-15-92</u>
TYPE OR PRINT NAME <u>John Hampton</u>	TEL EXT OR FNO.

(This space for State Use)

Original Signed by CHARLES GHOLSON
APPROVED BY _____ TITLE _____ DEPUTY OIL & GAS INSPECTOR, DIST. 3
CONDITIONS OF APPROVAL, IF ANY: _____ DATE **JUN 19 1992**

Gallegos Canyon Unit #109E
1/31/92 - 2/21/92

MIRUSU. NDWH. NUBOP. Killed well x 30 BW. TIH x TBG x tagged bottom @ 6127'/. TIH x RBP, PKR x TBG to 5897'. Set RBP x TOH x 1 STD TBG. RU pump x loaded CSG x KCL WTR. Set PKR. Press test plug to 1500#. Held. RU pump to CSG x press tes CSG to 1000#. Held. Released PKR x TOH x TBG. RU. TIH X CBL logged from 1500'to surface. TOH x Log. TIH x squeeze gun shoot 1' interval W/2 shots at 665'. TOH W/SQ gun. RU pump x circ 50 BW dwn. CSG x UP B.head. TIH x 7" PKR x TBG to 495', & set PKR. RU pump x circ b.head clean. RU x pumped 270 SX Class B CMT x 2% CACL AIP of 300# at 3 BPM. Circ 10 BBLS good CMT to pit. Displaced CMT x 6 BW. TOH x 7" PKR. TIH x bit x scrapper to 599' x tagged CMT from 599' to 672'. TIH x 7" PKR. and test Sq holes to 500psi. press. bled off. TOH x PKR. TIH x TBG opened ended to 685'. RU & pumped 5 BBLS CMT over perms @ 665'. TOH x TBG. RU CMT. Pumped 1.5 BW. Press squeeze holes to 1600#. Press CSG to 1600#. Held. Pumped apprx. 25 BBLS CMT into holes at 665'. TIH x bit & TAG CMT @ 630'. Drill CMT from 630' to 735'. Dropped out of CMT. TIH w/ RET. head x TBG. Circ sand off of plug. TIH & RET bridge plug. TOH x TBG x RBP. TIH w/ mule shoe, 1 JT, seating nipple, 195 JTS TBG. and landed tbg @ 6062'. NDBOP, NUWH. RDMOSU.