Form 3160-5 (November 1983) (Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR SUBMIT IN TRIPLICATES OCHER (10ther Instructions on rerefer side)

Budget Bureau No. 1004-0135
Expires August 31, 1985
5. LEASE DESIGNATION AND OBBIAL NO.

SF-078926

BUREAU OF LAND MANAGEMENT			SF-078926
	DTICES AND REPORTS (possals to drill or to deepen or plug b ICATION FOR PERMIT—" for such pi		S. IF INDIAN, ALLOTTER OR TRIBE NAME
1. OIL [] GAS []			7. UNIT AGREEMENT NAME
WELL X WELL OTHER 2. NAME OF PERATOR			Gallegos Canyon Unit 8. FARM OR LEASE NAME
Amoco Production Co.			9. WBLL RO.
501 Airport Drive, Far 4. Location of WELL (Report location See also space 17 below.) At surface		atte keaftheensoral	135 E 10. PIELD AND POOL, OR WILDCAT
1450' FNL x 1850' FEL	YAM	2 9 1985	Basin DK/Totah GLP EXT 11. BBC, T. R. M., OR BLK. AND BURNNY OR ARRA
14. PERMIT NO		AND MANAGEMENT PESOURCE AREA RT, CR. etc.)	SW/NE Sec 26, T29N, R13W 12. COUNTY OR PARISH 13. STATE San Juan NM
in Check A	opropriate Box To Indicate No	ature of Notice, Report, or O	
		• • •	ENT REPORT OF :
TEST WATER SHUT-OFF FRACTURE TREAT SHORT OF ACIDIZE REPAIR WILL (Other)	PUBLICAN ALTER CONTING MULTIPLE COMPLETE ABANDON* CHANGE PLANE	FRACTURE TREATMENT SHOUTING OR ACIDIZING (Other) (Note: Report results Completion or Recomple	ALTERING CABING ABANDONMENT ABANDONMENT A multiple completion on Well tion Beport and Log form.)
Moved in and rigged up and plugback depth is tested production casi	service unit on 4-25-6247'. Drilled out to ng to 3500 psi for 30', 6210'-6252', 4 jspf	85. Total depth of t a new plugback depth minutes. Perforated , .50" in diameter, f	of 6282'. Pressure the following Dakota or a total of 328 holes.
Landed 2-3/8" tubing a	t 6256' and released t	he rig on 5-1-85.	

18. I hereby cer ify the forestigk is true and correct SIGNED	TITLE Adm. Supervisor	ратю5-22-85
(This space for Federal or State office use)	TITLE	ACCEPTED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY:		JUN 04 1985

*See Instructions on Reverse Side