DISTRIBUTION		ATION DIVISION	Form C-102
	P. O. 80		Form C-103 Revised 10-1-
SANTA FE	SANTA FE, NEV	V MEXICO 87501	
FILE U.S.G.S.			Sa. Indicate Type of Lease
LAND OFFICE		,	State Fee XX
OPERATOR			5. State Oil & Gas Lease No.
			annanana -
too mot use this form for PRO	Y NOTICES AND REPORTS ON POSALS TO DRILL OR TO DEEPEN OR PLUG	BALK 10 A DIFFERENT NEBERTOIN.	
OIL CAS X			7, Unit Agreement Name
well well (A)	OTHER-		8. Form or Lease Name
Tenneco Oil Company			City of Farmington Con
Address of Cperator			9, Well No.
P.O. Box 3249, Engle	wood, CO 80155		1E
Location of well			10. Field and Pool, or Wildcat
UNIT LETTER	650 PEET FROM THE North	LINE AND 1650	Basin Dakota
, East		1 21.7	
THE LINE, SECTION	N 10 TOWNSHIP 29N	RANGE 13W	_ HMPM.
mmmm	15. Elevation (Show whether	DF. RT. GR. etc.)	12. County
	5345'	, 5, 11, 61, 61-1,	San Juan
	<u> </u>	Name of Name Paper	as Other Date
	Appropriate Box To Indicate 1		QUENT REPORT OF:
NOTICE OF IN	TENTION TO:	30832	QUENT REPORT OF.
	PLUS AND ABANDON	REMEDIAL WORK	ALTERING CASING
RFORM REMEDIAL WORK	Page and against [COMMENCE DRILLING OPHS.	X PLUS AND ABANDONMENT
MPORARILY ASAMOON	CHANGE PLANS	CABING TEST AND CEMENT JOB	
		OTHER	
OTHER			
		enils and sine nessiness dates i	ncluding estimated date of starting any propos
Describe Proposed or Completed Opwork) SEE RULE 1103.	erations (Clearly state all pertinent de	iuiis, unu give periinem uutes, i	increasing terminates mark of desiring may propose
See attached activit	y detail.		
		•	
		·	2 × 1983
·		·	
		·	2 \ 1983 OCAU JAN
		·	2 × 1983
		·	2 \ 1983 OCAU JAN
		·	2 \ 1983 OCAU JAN
		·	2 \ 1983 OCAU JAN
		·	2 \ 1983 OCAU JAN
, I hereby certify that the information	above is true and complete to the best		2 \ 1983 OCAU JAN
. I hereby certify that the information	above is true and complete to the best		2 \ 1983 OCAU JAN

SUPERVISOR DISTRICT # 3

____ JAN 2 1 1988

Original Signed by FRANK T. CHAVEZ

CITY OF FARMINGTON COM 1 E

12/02/87	ACTIVITY: DRILLING	MU BOP'S. Set 13 3/8" COND @ 63 w/125 SX, CIRC 7 BBLS TO SFS MIRU, DRL RAT & MOUSE HOLE. SPUD 11:45 am 12/2/87. SET & CMTD 12 JTS 9 5/8" CSG @ 518 w/265 SX CMT. FC @ 473. PD @ 12:45 AM, CIRC 23 BBLS CMT TO SFS. CMT TOP FELL BACK 4'. WOC 4 HRS BACKOFF LANDING JT & INSTALL CASINGHEAD. NU BOP'S.
12/03/87	ACTIVITY: DRILLING	RMG TO BTM. NU BOPE & PRESSURE TEST CSG BLIND RAMS, MANIFOLD, KILL & CHOKE LINE & PIPE RAMS TO 1500 PSI 30 MINS - CHKED OK. PU DC & TIH W/BIT #2. DRLG PLUG, CMT & SHOE. DRL & SVY TO KOP @ 1257'. CIRC PRIOR TO TOOH. TOOH & PU 1 1/2 DEG BENT SUB & 5" DELTA 500 MTR. TIH, SVY, ORIENT TOOLS & RM TO BTM.
12/04/87	ACTIVITY: DRILLING	DRL & SVY: SVYS: 2 DEG @ 1273, 5 DEG @ 1336, 7 DEG @ 1399, 7 1/4 DEG @ 1463 & 1526, 8 1/4 DEG @ 1589 & 9 DEG @ 1671.
12/05/87	ACTIVITY: DRILLING	DRL & SVY. WO DAYLITE FOR TIH. SVYS: 9 1/2 DEG @ 1764, 11 DEG @ 1858, 12 DEG @ 1952, 14 DEG @ 2043, 14 3/4 DEG @ 2136, 17 DEG @ 2230, 19 DEG @ 2323 & 19 1/4 DEG @ 2418. RAN 4 WL SVYS WITH 4 DIFF READINGS. CIRC & WO SVY TOOLS.
12/06/87	ACTIVITY:	CIRC, TOH FOR NEW BHA. LD MONEL & SHORT DC. PU NEW MONEL & EXT SUB. TIH, CIRC 1 HR. RAN SVY @ 100' STATIONS FROM TD TO SFS. DRL & SVY - SVY UNIT FAILED. SVYS: 20 3/4 DEG @ 2503, 21 3/4 DEG @ 2594, 22 1/2 DEG @ 2690, 23 1/2 DEG @ 2713 & 24 1/2 DEG @ 2877.
12/07/87	ACTIVITY: DRILLING	DRLG W/MOTOR. CIRC, RAN WL - 100' STATIONS. DRL & SVY TO 2996 POOH FOR MOTOR, LD BLD ASSEMBLY. PU BENT SUB, MOTOR & XO BITS TIH, WASH 30' TO BTM (20' FILL). REV. SVYS: MIN - 20 1/4 DEG @ 2500', MAX - 27 DEG @ 3243
12/08/87	ACTIVITY: DRILLING	SVY. 27 1/2 DEG @ 3338.
12/09/87	ACTIVITY: DRILLING	CIRC. W/O DAYLIGHT. DRLD & SVY.
12/10/87	ACTIVITY: DRILLING	
12/11/87	ACTIVITY: DRILLING	
12/12/87	ACTIVITY:	DRL & SVY. SVYS: 15 1/2 DEG @ 4959, 11 1/4 DEG @ 5065.
12/13/87	ACTIVITY: DRILLING	
12/14/87	ACTIVITY: DRILLING	