Form 3160-5 UNITED STATES DEPARTMENT OF THE INTERIOR *(December 1989) BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill, deepen or reentry to a different reserve Use "APPLICATION FOR PERMIT-" for such proposals SUBMIT IN TRIPLICATE 1. Type of Well: oil well gas well X 2. Name of Operator: Blackwood & Nichols Co., Ltd. OCT 2 5

4. Location of Well: (Footage, Sec., T., R., M., or Survey Description)

1360' FNL. 1670' FEL Section 24, T30N, R8M

TYPE OF SUBMISSION

__ Final Abandonment Notice

Notice of Intent

XX Subsequent Report

BUREAU RY NOTICES A	OF THE INTERIOR OF LAND MANAGEMENT ND REPORTS ON WELLS deepen or reentry to a different reservoir ERMIT-" for such proposals	5. Lease Designation & Serial # SF078615A 6. If Indian, Allottee/Tribe Name	
SUBMIT IN	TRIPLICATE	7. If Unit or CA, Agmt. Design.:	
oil well g	as well X other DECEI		
Blackwood & Nic	thols Co., Ltd. OCT 2 5 190	9. Well No.: 30-045-27817	
P.O. Box 1237,	Durango, CO 81302-1237 OIL CON.	DIV. Basin Fruitland Coal	
otage, Sec., T., R., FML, 1670' FEL n 24, T30M, R8W	M., or Survey Description)	11. County or Parish, State: San Juan, New Mexico	
CHECK APPROPRIATE BO	OX(s) TO INDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA	
BMISSION	TYPE OF ACTION		
ent	Abandonment	Change of Plans	
	Recompletion	_XX_ New Construction	
ort	Plugging Back	Non-Routine Fracturing	
	Casing Repair	Water Shut-Off	
	Altering Casing	Conversion to Injection	
ment Notice			
ment Notice	Other: (Note: Report results of more recompletion Report and	multiple completion on Well Completion Log form.)	
COMPLETED OPERATIONS proposed work. If		Log form.) re pertinent dates, including estimated	

13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and date of starting any proposed work. If well is directionally drilled, give subvertical depths for all markers and zones pertinent to this work.)*

Spud 12-1/4" surface hole at 7:00 p.m., 9-9-26-90 9-27-90 Run 8 jts (326.91') 9-5/8" 36# K-55 ST&C T Run notched collar on bottom. Cement with 250 sx (CaCl, and 1/4 #/sk celloflake. Run 15 Bbls water al Bbls water. Circulate 23 Bbls cement to surface. Pl 26-90. WOC. Cut off pipe, weld on bradenhead. Nip Tag cement and plug psi for 30 minutes - held OK. Drill new formation at 12:30 a.m., 9-27-90.

3. Address of Operator:

12.

continued on attached page	е		
14. I hereby certify that the foregoing is	true and correct.		
Signed: RNN Milly	ROY W. WILLIAMS	Title: ADMINISTRATIVE MANAGER	Date: 10/4/90
(This space for Federal or S	State office use)		
Approved By	ny: ACCEPT		FOR RECORD
		oct	1 8 199 0

the United States any false, fictitious, or fraudulent statements or representations as to FARMINGTON RESDURCETAREArisdiction.

9-30-90 Drill to TD of 2978'. Circulate, short trip, circulate. Lay down drill pipe and drill collars. Run 69 jts (2981.23') 7" 23# N-80 LT&C USS casing; shoe at 2977.86'; insert float at 2933.03'; centralizers on bottom 5 jts and turbalizers through Ojo Alamo. Cement with Howco. Run 20 Bbls mud flush ahead, cement with 440 sx (744 cf) 65/35 Poz with 6% gel, 1/4 #/sk flocele, and 0.6% Halid 322. Tail with 125 sx (148 cf) Class B with 1/4 #/sk flocele. Good circulation throughout job, circulate 25 Bbls cement to surface. Plug down at 8:30 p.m., 9-29-90. Float held OK.