Form 3160-5 (December 1989)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: September 30, 1990

5. Lease Designation and Serial No.

- 1						, ,	
- 4			~	F-	^	O.S	•
- 1	N	M		−-	L	20	

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill Use "APPLICATION FOR	6. If Indian, Alloyee or Tribe Name						
SUBMIT I	7. If Unit or CA, Agreement Designation						
1. Type of Well		8. Well Name and No.					
OIL GAS WELL OTH	Gallegos Canyon Unit 392						
2. Name of Operator	9. API Well No.						
Amoco Production Company	30-045-28264						
3. Address and Telephone No.	10. Field and Pool, or Exploratory Area						
P.O. Box 3092 Houston, TX 7725	Basin Fruitland Coal						
4. Location of Well (Footage, Sec., T., R., M., or Survey	11. County or Parish, State						
1035' FSL 1110' FWL Sec 26 T29	San Juan New Mexico						
12. CHECK APPROPRIATE BOX(s	s) TO INDICATE NATURE OF NOTICE, REPOR						
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent	■ Abandonment	Change of Plans					
Subsequent Report	Recompletion	New Construction					
Final Abandonment Notice	☐ Plugging Back☐ Casing Repair☐	Non-Routine Fracturing Water Shut-Off					
Final Adamdonment Notice	Altering Casing	Conversion to Injection					
	Other						
	(Note: Report results of multiple or Recompletion Report and Log form	ompletion on Well Completion or					
Amoco Production Company reques procedure.	rly state all pertinent details, and give pertinent dates, including ations and measured and true vertical depths for all markers and zet permission to Plug & Abandon the subject well are the subjec	per the attached well work					
14. I hereby certify that the foregoing is true and correspond with the foregoing is true and correspond to the foregoing is t	ct (ĈĈ _{Title} Permitting Assistant	Date08/21/00					
(This space for Federal or State office use)							
Approved by	Title	Date 9/5/00					
Title 18 U.S.C. Section 1001, makes it a crime for any or fraudulent statements or representations as to any magnetic statements.	person knowingly and willfully to make to any department or age atter within its jurisdiction.	ency of the United States any false, fictitious					

GCU 392 (FC)

Original Completion: 11/90 TD =1,795' PBTD = 1,705'

Objective: PXA entire wellbore

Page 2 of 2

- 1. Notify regulatory agencies (BLM, NMOCD, FIMO) 24 hours in advance of plugging activity. Contact BLM and indicate well is allotted (FIMO regulations effective April 1, 1997).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 4. TOH with 2 3/8" tubing. TIH with 2 3/8" tubing workstring and CIBP. Set CIBP at 1,500' and spot cement plug from 1,500' to 1,400' (12 sacks). TOH to 1,039', spot cement plug from 1,039' to 939' (12 sacks). TOH to 195', spot cement plug from 195' to surface (23 sacks).
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Contact FMC and ship surface equipment to yard or other location per instructions.
- 7. Provide workorder to Buddy Shaw for reclamation.
- 8. Rehabilitate location according to BLM or State requirements.

GCU 392 (FC)

M25 T29N-R13W 1035' FSL, 1110' FWL API 3004528264 SF-087926-A

Proposed PXA Wellbore Schematic

