

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-045-29225

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Woods Gas Com B

8. Well No.

1

9. Pool name or Wildcat

Kutz Pictured Cliffs, West

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

BP America Production Company

Attn: Cherry Hlava

3. Address of Operator

P.O. Box 3092 Houston, TX 77253

4. Well Location

Unit Letter M 1520 feet from the South line and 1150 feet from the West line

Section 7 Township 29N Range 12W NMPM San Juan County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

5476'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Routine Frac Same Sand ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

On 1/23/02 BP America Production Company frac'd the Pictured Cliffs formation & landed Tbg @1492'.

We respectfully request to Temporary Abandon this well in order to hold the Pictured Cliffs for future gathering system upgrade.

Please see the attached procedure.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cherry Hlava TITLE Regulatory Analyst DATE 07/11/2002

Type or print name Cherry Hlava Telephone No. 281-366-4081

(This space for State use)

APPROVED BY ORIGINAL SIGNED BY CHARLES T. PEREZ TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #8 DATE JUL 15 2002

Conditions of approval, if any:

San Juan Basin Well Work Procedure

Well Name: Woods Gas Com B 1
Version: #1
Date: 7/10/2002
Budget: DRA
Repair Type: Temporary Abandonment

Objectives:

1. TXA wellbore; hold Pictured Cliffs for gathering system upgrade.

Pertinent Information:

Location:	Sec 7 T29N R12W	Horizon:	Pictured Cliffs
County:	San Juan	API #:	30-045-29225
State:	New Mexico	Engr:	Allen Kutch
Lease:		Phone:	(281)366-7955

Bradenhead Test Information:

Test Date:	Tubing:	Casing:	BH:
------------	---------	---------	-----

Time	BH	CSG	INT	CSG
5 min				
10 min				
15 min				

Temporary abandonment procedure

1. Contact State agencies prior to starting P&A work (NMOCD Charlie Perrin, 505-334-6178 X16).
2. Check location for anchors. Install if necessary. Test anchors.
3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
4. ND wellhead. NU BOP's.
5. POOH with 1493' of 2-1/16" tbg, visually inspecting.
6. Make scraper run.
7. TIH with 3-1/2" 9.3# CIBP on tbg. Set CIBP at 1450' to TXA the Pictured Cliffs perms.
8. Load well with inhibited lease water.
9. Attach chart recorder. Test casing to 550 psi for 30 minutes. Fax copy of chart to 281-366-0700, attention Allen Kutch.
10. Land 2-1/16" tbg. ND BOP, NU WH.
11. RDMO SU.

Woods Gas Com B 1 - Proposed T&A Configuration
San Juan County, NM
Unit M Section 7 T29N - R12W
Run 23

7-07-2002
ATK

KB: 13' above GL

