

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-045-29370
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name  GOLDEN BEAR
8. Well No. 1
9. Pool name or Wildcat FLUCHER KUTZ PICTURED CLIFF EXT

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator ROBERT L. BAYLESS	
3. Address of Operator P.O. BOX 168 FARMINGTON, NM 87499	
4. Well Location Unit Letter P : 1081 Feet From The SOUTH Line and 1031 Feet From The EAST Line Section 2 Township 29N Range 13W NMPM SAN JUAN County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5402'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: SPUD AND RUN SURFACE CASING <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SEE ATTACHED MORNING REPORT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE PRICE M. BAYLESS TITLE ENGINEER DATE 9/9/96  
TYPE OR PRINT NAME: PRICE M. BAYLESS TELEPHONE NO. 326-2659

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE SEP 10 1996  
CONDITIONS OF APPROVAL, IF ANY

# **ROBERT L. BAYLESS**

Golden Bear #1  
1081 FSL & 1031 FEL  
SECTION 2, T29N, R13W  
San Juan County, New Mexico

## **MORNING REPORT-DRILLING**

- 9-4-96 Move in L&B Speed Drill and rig up. Dig drilling pit.
- 9-5-96 Spud well at 12:00 noon. Drill 8 3/4" hole to 45 feet and hit boulders. Mix mud and drill to 65 feet. Trip for bit. Trip in with Bit #2 and drill to 110 ft. Shut down overnight with drywatchman.
- 9-6-96 Trip in hole and drill to 167 ft. Drop survey. Trip out of hole. Deviation 1/4° at 167 feet. Attempt to run casing, stopped at 50 feet. Pick up 10 3/4" bit and ream hole to 167 feet. Trip out of hole and run 4 joints (164.40 feet) of new 7" 23 #/ft J-55 ST&C casing. Land casin at 166 feet. Rig up Cementers Inc and cement with 105 sx Class B cement with 2% CaCl and 1/4 lb celloflake per sack. Good circulation throughout job with 5 bbl good cement circulated to pit. Plug down at 7:30 pm, 9-5-96. Shut down overnight with drywatchman.
- 9-7-96 Nipple up BOP and pressure test casing to 600 psi for 30 minutes. Test pipe rams and blind rams, held OK. Trip in hole and tag cement at 125 feet. Drill out cement and start new formation. Drill 6 1/4" hole to 380 feet. Shut pipe rams. Shut down overnight with drywatchman.
- 9-8-96 Drill 6 1/4" hole to 520 feet. Drop survey tool. Trip for bit. Deviation 1/2° at 520 feet. Test blind rams. Trip in hole with Bit #5. Drill to 1000 ft. Run survey, 3/4° at 1000 feet. Shut pipe rams. Shut down overnight.
- 9-9-96 Drill 6 1/4" hole to 1265 feet. Shut pipe rams. Shut down overnight with drywatchman.