

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
100 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

1. Type of Well:
OIL WELL GAS WELL OTHER

Hargis

2. Name of Operator
Kerr-McGee Corporation

8. Well No.
/

3. Address of Operator
P. O. Box 11050, Midland, TX 79702

9. Pool name or Wildcat
Fulcher-Kutz PC

4. Well Location
Unit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line
Section 33 Township 30N Range 12W NMPM San Juan County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING CPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up, pull rods and pull tubing.
2. GIH to PBDT (1768'), circulate hole with 20 sacks. ETOC 1350'. Test 4" to 500 psi.
3. GIH and perforate 4" at 1150'. Circulate balanced plug in 4" and 7" from 1150-950' (35 sks). Test plug to 500 psi.
4. GIH and perforate 4" and 7" at 500'. Circulate balanced plug in 4" and 7" and outside 7" from 500' to surface (70 sks).
5. Set dry hole marker and clean location.

RECEIVED
JAN - 7 1993
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stephen N. Landgrave TITLE District Supt. DATE 1-4-93

TYPE OR PRINT NAME Stephen N. Landgrave TELEPHONE NO. 915 688-7023


(This space for State Use)

APPROVED BY Original Signed by CHARLES GHOLSON TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 3 DATE JAN - 7 1993

CONDITIONS OF APPROVAL, IF ANY:

SPUD - SEPT 1944
W/O - SEPT 1961

HARGIS #1



SPUD - SEPT 1944
W/O - SEPT 1961

HARGIS #1

