Form 3 160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 3 1,1993

NM 02491

5. Lease Designation and Seriai No

6. If Indian, Allonee or Tribe Name

# SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICA TE		7. It offices, Agreement Designation
1 Type of Well		
Oil Gas Well Other	8. Well Name and No.	
2 Name of Operator		Federal A #1
CONOCO INC.	9. API Well No.	
3. Address and Telephone No	30-045-09192	
10 DESTA DR. STE. 100W, MIDLAND, T	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T. R. M. or Survey Descrip	Basin Dakota (71599)	
Section 27, T-30-N, R-11-W, F		11. County or Parish, State
1850' FNL	& 1850' FWL	
		San Juan. New Mexico
CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, F	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Repon	Plugging Back	Non-Routine Fractung
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		INote: Reporresuits of multiple compition on Wd1 Completion or Recompletion Report and Log form.)
13 Describe Proposed or Completed Operations (Clearly state ail pert- give subsurface locations and measured and true vertical displayed and true vertical displayed.)	tinent details, and give pertinent dates, including estimated date epths for all markers and zones pertinent to this work.)*	of starting any proposed Aork If well is directionally drilled.

It is proposed to repair the casing leak in this well using the attached procedure.

OIL COM. DIV.

Signed Signed		Kay Maddox	
	Title	Regulatory Agent	Date May 27, 199
(This space for Federal or State office use)			
Approved by Conditions of approval if any	Title		Date

BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FILE ROOM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false. Ectitious or fraudulent statements or representations as to any matter within its junsdiction

## Federal A #1 Slim Hole/Casing Leak Repair May 21, 1998

API# 300450919200

Location: Sec. 27, Twn. 30N, Rge. 11W, Quarter NW SE NW, 1850' FSL, 1850' FEL, San Juan County.

We request funds in the amount of \$65,000 to pull retrievable bridge plug, run and cement 2-7/8"slim hole completion on the Federal A #1. The Federal A #1 well is under plug due to a previous casing leak to prevent fluid invasion from a wet upper zone. The well is currently temporarily abandoned and should recover to above 100 Mcfgd. The well now needs casing repair in the form of slim hole to be in compliance with regulations pertaining to wells with casing leaks.

#### Work Plan

Casing leaks were isolated between 745' and 808' and determined to be non-repairable with conventional cement squeeze methods. We propose to run 2-7/8" EUE 8rd tubing with Arrow Completion System Watson-440 full bore packer and set packer 200' above top perforation and end of tubing just above top perforation at 6,790'. We will cement the 2-7/8" slim hole string from above packer to surface, drill out cement and plugs, set a collar stop spring near bottom, and optimize production with plunger lift.

## **Completion Data:**

Spud date: 12/22/63 Completion: 01/02/64

TD = 6.930' PBTD = 6.903' KB-Grd = 12' Elev. Grd = 5.933'

Surface Casing: 8-5/8", 24#, 10 its. set @ 314' (cmt. to surface)

Production Casing: 4-1/2", 11.6#, J-55 8rd, 1 jt. to 22'
4-1/2", 10.5#, J-55 8rd, 214 jts. to 6,729' (TOC unknown. DV@ 2,461'.)
4-1/2", 11.6#, J-55 8rd, 6 jts. to 6,929' (1st stg 150 sx, 2nd stg 550 sx.)

RBP - Halliburton R-4 Plug @ 6,703' inside 4-1/2", 10,5#, J-55 8rd, casing.

Production Tubing: 2-3/8", 4.7#, J-55 8rd, 210 jts. hung @ 6,628' w/1.78" ID SN on bottom.

Perforations: Dakota - 6,790' - 6,810', & 6,840' - 6,885'
(4 spf @ 6881-85, 2 spf @ 6840-50, all in 500 G 7-1/2% MCA

**Note:** Casing leak isolated between 745' and 808', able to circulate to surface pipe, unable to blow down surface pipe. Recommend pumping tubing displacement volume of dyed water ahead of cement when cementing 2-7/8" slim hole string. Drop displacement plug when dyed water reaches surface.

## Federal A #1 Slim Hole/Casing Leak Repair May 21, 1998

#### 1. Pre Work

- A. Locate and test deadman anchors. Spot flow back pit (20x20) and prepare. Inform operator of work to be done and time frame. Check for location size and equipment placement. Identify any hazards (power lines, H2S, tight equipment fits).
- B. Have pressure gauges on both casing and tubing when necessary (during acid, frac, testing).
- C. Hold Safety Meeting before rigging up to discuss potential hazards and meeting place in case of an emergency.

## 2. Pull Tubing

- A. RU. Blow well down and kill with minimum amount of 1% KCl. NU BOP's. The well should be dead as it is under a RBP.
- B. POOH 210 jts. 2-3/8", 4.7#, J-55, EUE tubing w/SN on bottom.
- C. RIH with work string and over shot and pull RBP @ 6,700'.
- D. POOH work string standing back.

### 3. RIH, Scrape Casing, Tag Fill, & Clean Out

- A. RIH with work string, casing scraper, tag fill, clean out to bottom with 3-7/8" bit (PBTD 6903') circulating with nitrogen. (4.5",11.6#, csg. has drift of 3.875)
- B. POOH work string laying down.

#### 4. SLIM HOLE

- A. TIH, run three 2-7/8" pup joints on bottom, pick up Watson-440 packer at 200',
- B. Run aluminum blank disc in collar above packer with short ported nipple above it. TIH to set EOT @ 6,790', top perforation is at 6,790'
- C. Set packer 200' above top perforation with end of tubing at or just above 6,790'. **NOTE:** Check set load and cement load to prevent packer shear release.
- D. Pump 38 barrels dyed water ahead of cement, annular cement volume between 2-7/8", 6.5# tubing & 4-1/2", 10.5# casing is 52 bbls. or 292.6 cu. ft.. When dyed water reaches surface drop displacement plug.

### 6. Return Well to Production

Notify operator to install plunger lift on 2.875" casing/tubing and resume production. Watch fluids production and optimize plunger lift. Monitor well for rate at least one week. Change orifice plate, check separating/compression facilities-- notify engineering for assistance, if needed, in making equipment changes.

San Juan West Team