

October 7, 1958

Mr. Elvie Uta  
Oil Conservation Commission  
Santa Fe, New Mexico

Re: 1958 annual packer test,  
EPNG #10 Ludwick, 29-30N-10W

Dear Elvie:

I checked the data of subject test with the company gas engineering department before I okayed the test.

I do not believe the packer to be leaking. Here are some of the several possibilities which could have caused the reaction:

1. Temperature decreases due to flush Mesaverde production following a three-week shut in.
2. The use of Pictured Cliffs gas to clean out the deadweight connections.
3. Low oil volume in deadweight.
4. Transposition of numbers from 497 to 479.
5. Unauthorized persons tampering with well.

I cannot agree to leakage since the pressure rebuilt to the same build-up curve after the faulty reading. The company advises that they have found no indication of a leak.

Thanks for checking with us on this matter.

Yours very truly

A. R. Kendrick  
Engineer, District #3

ARK:ks

October 11, 1958

Mr. Elise G. S.  
Oil Conservation Commission  
Suite 101, New Mexico

Re: 1958 annual pocket test,  
LBNW #10 Lambshead. 29-30W-10W

Dear Sirs:

I checked the data of subject test with the company and engineering department before I checked the test.

I do not believe the proper to be lacking. There are some of the several possibilities which could have caused the reaction:

1. Temperature decrease due to finish mechanical production following a three-week shut in.

2. The use of Pictured Giff's gas to clean out the deadweight connections.

3. Low oil volume in Lambshead.

4. Transposition of numbers from 497 to 498.

5. Unauthorized persons tampering with well.

I cannot agree to indicate when the pressure would be to the same during-up curve after the fairly reaching. The company states that they have found no indication of a leak.

Thanks for checking with us on this matter.

Yours very truly

A. E. Kendrick  
Engineer, District #3

ANK:ra

GOVERNOR  
EDWIN L. MECHEM  
CHAIRMAN

## New Mexico

### OIL CONSERVATION COMMISSION

LAND COMMISSIONER, MURRAY E. MORGAN  
MEMBER

STATE GEOLOGIST, A.L. PORTER JR.  
SECRETARY DIRECTOR



P. O. Box 871  
Santa Fe, New Mexico

October 3, 1958

Mr. Emery Arnold  
Oil Conservation Commission  
Aztec, New Mexico

Re: Annual Packer Leakage Test  
El Paso Natural Gas Company's  
Ludwick No. 10- 29-30-10

Dear Emery:

In checking the above captioned packer leakage test, it looks to me as though there was a good possibility of packer leakage as shown on the graph from May 7 to 11. Perhaps you have some explanation or possibly this has been remedied.

I have been from August 11 getting around to this so it is possible that you have already remedied the situation, however, it has an OK by Al.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Elvis".

ELVIS A. UTZ

EAU:omg

