

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

RECEIVED
DEC 10 1997
OIL CON. DIV.

5. Lease Number
SF-078116A
6. If Indian, All. or
Tribe Name
7. Unit Agreement Name

2. Name of Operator
DIST. 3
**BURLINGTON
RESOURCES**
OIL & GAS COMPANY

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number
Florance #3
9. API Well No.
30-045-09290
10. Field and Pool
Blanco Pict. Cliffs
11. County and State
San Juan Co, NM

4. Location of Well, Footage, Sec., T, R, M
1156' FSL, 790' FWL, Sec. 21, T-30-N, R-9-W, NMPM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other - Bradenhead repair
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

- 10-3-97 MIRU. ND WH. NU BOP. TIH, tag fill @ 2722'. TOOH w/84 jts 1 1/4" tbg. Drop 7 sx sd down 2 7/8" csg. SD for weekend.
- 10-6-97 Load csg w/18 bbl Kcl wtr. PT csg to 1000 psi, failed. TIH w/pkr, set @ 1530'. PT csg to 1000 psi up backside, OK. PT sd plug, failed. Reset pkr @ 2420'. PT csg to 1000 psi/15 min, OK. PT sd plug, failed. TIH to sd plug @ 2507'. TOOH w/pkr. Pkr parted coming out of hole. SDON.
- 10-7-97 TIH, w/fishing tools. Fishing. Dump 3 sx sd down 2 7/8" csg. SDON.
- 10-8-97 Load hole. PT sd plug, failed. TIH, ran CBL @ 0-2400', TOC on 2 7/8" csg @ 2260'. Tag sd plug @ 2432'. (Verbal approval to squeeze from Ernie Busch, OCD). TIH, perf 1 sqz holes @ 1100'. TOOH. Establish injection. Circ hole clean. TIH, perf 2nd hole @ 1100'. TOOH. Establish injection. Pump 250 sx Class "B" neat cmt w/2% calcium chloride. Displace w/wtr. TIH, clean cmt out to 760'. TOOH. Sqz to 1000 psi. SDON.
- 10-9-97 TIH, tag TOC @ 771'. Drill cmt @ 771-1083'. SDON.

Continued on back

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 12/2/97

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

ACCEPTED FOR RECORD

DEC 05 1997

FARMINGTON DISTRICT OFFICE

10-10-97 TIH, drill cmt @ 1083-1130'. Circ hole clean. Load hole. PT csg to 1000 psi. Sd plug still leaking. TOOH. TIH, ran CBL @ 0-1420', cmt @ 742-1242'. TOOH. TIH, shot 2 sqz holes @ 410'. TOOH. Establish injection. Circ hole clean. Pump 230 sx Class "G" neat cmt w/2% calcium chloride. Displaced w/1.8 bbl wtr. WOC. SD for weekend.

10-13-97 TIH, tag TOC @ 300'. Drill cmt @ 300-423'. Load hole. PT csg to 1000 psi, failed. Establish injection. Pump 20 sx Class "G" neat cmt w/2% calcium chloride. Sqz to 1000 psi. WOC. SDON.

10-14-97 TIH, tag TOC @ 385'. Drill cmt @ 385-398'. WOC. SDON.

10-15-97 TIH, tag TOC @ 398'. Drill cmt @ 398-442'. TOOH. Load hole. PT csg to 1000 psi, failed. TIH w/2 7/8" csg scraper to 410'. Tag tight spot in csg. TOOH. SDON.

10-16-97 TIH w/tapered mill to 410'. Mill to 1100'. Circ hole clean. TOOH w/mill. TIH pkr, set @ 490'. Load hole. PT csg up backside to 1000 psi, failed. PT csg below pkr, failed. TOOH w/pkr. Circ hole clean. Pump 8 sx Micro Matrix cmt w/3% calcium chloride. Displaced w/1.5 bbl. Sqz to 785 psi. WOC. SD for weekend.

10-20-97 TIH, tag TOC @ 258'. Drill cmt @ 258-410'. Load hole. PT csg to 500 psi, failed. TOOH. TIH w/2 7/8" csg scraper. TOOH. TIH w/2 7/8" pkr, set @ 480'. Load hole. PT csg to 1000 psi, failed. TOOH w/pkr. Establish injection. Pump 13 sx Class "B" neat cmt w/2% calcium chloride. Sqz to 1500 psi. WOC. TIH, tag TOC @ 255'. TOOH. Sqz to 1500 psi. WOC. SDON.

10-21-97 TIH, tag TOC @ 254'. Drill cmt @ 254-329'. WOC. SDON.

10-22-97 TIH, tag TOC @ 329'. Drill cmt @ 329-415'. Load hole. PT csg to 500 psi, failed. TOOH. Reset pkr @ 420'. Load hole. PT csg to 500 psi, failed. Reset pkr @ 386'. Load hole. PT csg @ 0-386' to 500 psi, OK. TOOH w/pkr. SDON.

10-23-97 Blow well & CO. SDON.

10-24-97 Pump 20 sx Micro Matrix cmt w/micro flyash, 50/50 mixer. Pump 25 sx Class "B" neat cmt w/2% calcium chloride. Sqz to 1500 psi. Displace 3.7 bbl cmt behind 2 7/8" csg. WOC. TIH w/bit, CO cmt to 264'. TOOH. Pressure up csg to 1000 psi. WOC. SD for weekend.

10-27-97 TIH w/bit, tag TOC @ 264'. Attempt to circ 2 7/8" csg w/wtr. Tbg is obstructed. TOOH. Float was plugged. TIH, drill cmt @ 412-455'. TOOH. TIH w/tapered mill to 455'. TOOH. SDON.

10-28-97 TIH w/pkr, set @ 480'. Load hole. PT csg to 500 psi, failed. Reset pkr @ 420'. Load hole. PT csg to 500 psi, failed. Reset pkr @ 395'. PT csg above pkr to 500 psi, OK. TOOH w/pkr. TIH, blow well & CO to 2474'. TOOH. SDON.

10-29-97 (Verbal approval to set packer 50' above formation for one year from John Keller, BLM & Frank Chavez, OCD). TIH w/fishing tools, tag sd @ 2474'. Blow well & CO. Establish circ. Tag fish @ 2511'. Fishing. SDON.

10-30-97 Fishing. TOOH w/fish & fishing tools. SDON.

10-31-97 TIH, tag up @ 2516'. Blow well & CO. TOOH. Circ hole clean. SD for weekend.

11-3-97 TIH, tag up @ 2732'. Blow well & CO to PBTD @ 2788'. SDON.

11-4-97 Blow well & CO. SDON.

11-5-97 Blow well & CO. TOOH. TIH w/pkr & 83 jts 1 1/4" 1.9# IJ tbg; set pkr @ 2659', landed tbg @ 2724'. ND BOP. NU WH. RD. Rig released.