DISTRIBUTION SANTA FE FILE U.E.G.S. LAND OFFICE TRANSPORTER GAS PROGRATION OFFICE

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe. New Mexico

(Form C-104) Revised 7/1/57

REQUEST FOR (OIL) - (GAS) ALLOWAPLE

New Well Recompletion

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which Form C-101 was sent. The allowable will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar able will be assigned effective 7:00 A.M. on date of completion or recompletion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Gas must be reported on 15.025 psia at 60° Fahrenheit.

ARE	HER	EBY REQ	UESTIN	G AN ALLOW n Corp. S	ABLE FOR	A WELL KN	OWN AS:	SV	(Date) SW 1/4,
(Company or Operator)			tor) 21	T 30N R 12W NMPM, Flora Vista - Mesaverde					
Unit Later San Juan				County. Date Spudded Total Depth 6560 PBTD					
P	lease is	ndicate loc	ation:	Top Oil/Gas Pa	y 34491	Name	of Fred. Form.	Hesaver	de
7	C	В	A	PRODUCING INTE	RVAL -	9451, 8 345		hes)	
<u>. </u>	F	G	Н	Open Hole		Depth Casir	ng Shoe 6535	Depth Tubing	6234 (Kd)
L	K	J	I	Natural Prod.	Test:	bbls.oil,	bbls water	er inhrs	Choke min. Size
M	N	0	P	Test After Ac load oil used GAS WELL TEST	b):b)	ols,oil,	bbls water i	n'hrs,	equal to volume of Choke min. Size
	/ En	OTAGE) and Gemen	ting Recor	rd Method of Tes	sting (pitot,	back pressure, e	tc.):	MCF/Day; Hou	rs flowed
	re	Feet		Test Aiter A	2 /h	- F Tooting:	apan flow		
Su		304	150	Choke Size_	. 3/4 Method	cf Testing:	epen Tion	d, such as aci	d, water, oil, and
8u			150	Choke Size Acid or Fraction	Method	cf Testing: [Give amounts of	f materials use	ed, such as aci	d, water, oil, and
8u	5/8 1/2	304		Acid or Fragand):	Method	Give amounts of Date fir oil run	of materials use	ed, such as aci	d, water, oil, and
8 4	5/8 1/2	304 6535	425	Acid or Fragand):	Method ture Treatment 9390 Tubirg Press.	cf Testing: [Give amounts of	f materials use 100 same st new to tanks	d, such as aci	d, water, oil, and
8 4 3/8	5/8 1/2	304 6535 6234	425	Acid or Fragand): Casing Fress. Oil Transpor	Method ture Treatment 9390 Tubirg Press.	Give amounts of Date fir oil run	f materials use 100 same st new to tanks	ed, such as aci	d, water, oil, and
8 4 3/8	5/8 1/2 8	304 6535 6234	425 (Kd	Acid or Fragand): Casing Fress. Oil Transpor	Tubirg Press.	Cf Testing: Cive amounts of the color of th	f materials use Off send st new to tanks	DEC.1	1 1962
8 4 3/8 email	5/8 1/2 8 rks:	304 6535 6234 y certify th	425 Kd nat the ini	Choke Size Acid or Fraces and): Casing Fress. Cil Transpor Gas Transpor	Tubing Press. ter Mcl ter 11	Cf Testing: [Give amounts of the state of t	of materials use of materials use to tanks to tanks to the best of the stern Tran	DEC.1	d, water, oil, and