

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

N.M. 09867-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR R. E. Drilling Co., Inc.	8. FARM OR LEASE NAME Lunt
3. ADDRESS OF OPERATOR P.O. Box 327, Farmington, N.M. 87401	9. WELL NO. 66
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1690' BSL, 990' SWL Sec. 17-T-30N-R-13W 5.5 to. Mex.	10. FIELD AND POOL, OR WILDCAT Basin Dakota
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T-30N, R-13W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5600'	12. COUNTY OR PARISH 13. STATE San Juan N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Round trip 2" tbg. and replace 1 bad joint. Sting into packer. Seal assembly U.M.
2. Squeeze Dakota perfs 6181-6052 with 35 sx to 2000 psi. Pull tbg. out of Pak. Spot 5 sx on top Pak.
3. Pull tbg. spotting 15 sx plug 5110-5260' and 15 sx plug 3750'-3900'.
4. Cut and pull 4 1/2 casing to 3500'.
5. Spot 35 sx plug 3550-3450', spot 50 sx plug 2900'-3050', spot 35 sx plug 1375'-1475', spot 15 sx plug 240'-195' spot 10 sx surface plug. Weld on plate 3' below surface.

RECEIVED

DEC 8 1976

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

U. S. GEOLOGICAL SURVEY
WASHINGTON, D. C.
DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

AUG 06 1984

*See Instructions on Reverse Side

M. M. C. P.

M. MILLENBACH
AREA MANAGER