

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**OIL CONSERVATION DIVISION**  
P. O. BOX 2088  
**SANTA FE, NEW MEXICO 87501**

Form C-100  
Revised 10-1

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL  GAS WELL  OTHER

1. Name of Operator: Meridian Oil Inc.  
2. Address of Operator: PO Box 4289, Farmington, NM 87499  
3. Location of Well: UNIT LETTER 1750 FEET FROM THE North LINE AND 660 FEET FROM East TOWNSHIP 30N RANGE 11W NMPM.  
4. Elevation (Show whether DF, RT, GR, etc.): 5608'GL  
5. County: San Juan

7. Unit Agreement Name  
8. Farm or Lease Name: Montgomery  
9. Well No.: 1  
10. Field and Pool, or Wildcat: Aztec Pic.Cliffs

**Check Appropriate Box To Indicate Nature of Notice, Report or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTERING CASING   
TEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT   
PULL OR ALTER CASING  OTHER  CASING TEST AND CEMENT JOB   
OTHER

6. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is intended to plug & abandon this well in the following manner:

MOL&RU. Install BOP & test operations. Pull 1" line pipe used for tbg. PU 2" work string and TIH to TD of 2044'. Circ. well w/9#/gal.mud. Spot plug from TD to 1628'. Use 60 sx (70.8 cu.ft.) C1 "B" neat. Plug will cover from TD to 50' above Fruitland formation.

TOOH. WOC 6 hrs. RU perforators. Perf two squeeze holes @ 696'. PU cmt. retainer & stinger-setting tool on tbg. TIH, set retainer @ 540 (top of Ojo Alamo).

PU tbg to test position, test tbg to 1000#. Lower tbg to pump position, displace 50 sx (59 cu.ft.) below retainer. Pull out of retainer, spot 6 sx C1 "B" (7 cu.ft.) plug on top of retainer. Plug to cover from 50' below Kirtland top to 50' above Ojo Alamo top.

TOOH, RU perforators. Perf 2 squeeze holes @ 140'. Circ. 40 sx (47 cu.ft.) C1 "B" neat cmt. plug down 5 1/2" csg. & back to surface in annular space.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Cut off wellhead, install dry hole marker w/10 sx (11.8 cu.ft.) C1 "B" neat cmt. Jerry Doak TITLE Drilling Clerk (WDW) DATE 3-22-88

APPROVED BY Original Signed by FRANK T. CHAVEZ SUPERVISOR DISTRICT DATE MAR 24 1988

CONDITIONS OF APPROVAL, IF ANY: