

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

OK
May 22, 1964

Union Texas Petroleum Co.
Suite B-400, 1740 Broadway
Denver 2, Colorado

Re: Possible casing failure,
Union Texas #1-X Johnson
SW $\frac{1}{4}$ Sec. 12-30N-9W

Gentlemen:

A field investigation by personnel from this office has disclosed several gas seeps in the vicinity of the above well. Most of these are located in the bottom of Pump Canyon, which is adjacent to this location.

Although this evidence is not conclusive in proving that the Johnson 1-X is the offending well, the proximity of these gas seeps to the well bore indicates the probability of casing failure in this well.

We are, therefore, directing that tests be run immediately to determine the condition of the casing in this well. Please contact this office prior to moving a rig on the location for tests and we will furnish a witness from this office.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA:ks

cc: Mr. Frank O'Halloran
Aztec, New Mexico

OIL CONSERVATION COMMISSION
1000 RIA BRAZOS ROAD
AZTEC, NEW MEXICO

1954

Mr. [Name] - [Address]
[City] - [State]

Dear Mr. [Name]:

The Commission is interested in the conservation of oil resources in your area. We are currently conducting a study of the oil reserves in the state and would like to know more about the oil resources in your area. If you have any information regarding the oil resources in your area, we would appreciate it if you would contact us at the address given below.

Very truly yours,

[Name]
Director, Commission

Enclosed please find [Number] copies of [Document Name].