(1	Feb. 1	951)	
			ŀ

Form 9-331a

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land	Office	Sente	7•	
Lease	No	78336		
Ilmit		Sec.		

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.		SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF REPORT
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT.
NOTICE OF INTENTION TO PULL OR ALTER CASING	1	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		
•	- 1	- FEW

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

			June 12	1	02
Well No. is located	tedft. f	$\operatorname{rom}_{-}\left\{ \begin{matrix} N \\ S \end{matrix} \right\}$ line	and 590 ft. from	$\left\{ egin{array}{c} E \\ W \end{array} \right\}$ line of sec. 11	l
SW/4, Section 11	30-7	9-4	IXM		
(1/2 Sec. and Sec. No.)	(Twp.)	(Range) Juan	(Meridian)	r Hextoo	
(Field)	(Cor	ınty or Subdivision)	(St	ate or Territory)	
The elevation of the derrick	floor above sea	level is	ft. <sup>G</sup> • L•		

## **DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Killed well w/water, pulled tubing, ran one 7" 17# to 24# Lane Wells HCCL packer set at 4402'. 25 jts. of 2-3/8" (768') below packer and 144 jts. of 2-3/8" tubing above packer. Tubing landed at 5179'. Sumbbed well in. Well on sales line 6/1/62.



I understand that this plan of work must receive approval in write DELHI-TAYLOR OIL CORPORATION Company	ting by the Geological Survey before parations may be commenced.
P. O. Dresser 1195 Address	
farmington, New Mexico	Original signed by  By G. T. HIGGINBOTHAM  By G. T. HIGGINBOTHAM
	District Superintendent Title
	GPO 918507