Form Approved.

UNITED STATES

	Budget	Bureau	No. 42-1	R1424
LEASE				
NM-024158				
IE INDIAN ALL	OTTEE (NO TOU	C. NIANA	_

DEPARTMENT OF THE INTERIOR	NM-024158 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
GEOLOGICAL SURVEY			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME		
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME		
1. oil gas well other	McKenzie B a s		
2. NAME OF OPERATOR	ୀ ବୃକ୍ତ ହିଁ ଜଣିଷ		
Tenneco Oil Company 3. ADDRESS OF OPERATOR	Basin Dakota		
720 S. Colo. Blvd., Denver, CO 80222	11. SEC., T., R., M., OR BLK. AND SURVEY OF		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA স্থানী বিশ্বস্থানী বিশ্ব		
AT SURFACE: 1850 FSL, 1850 FWL	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan - TE New Mexico		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO. 3555 4 0 0 0 0		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5728 'GR (37 - 57 - 57 - 57 - 57 - 57 - 57 - 57 -		
TEST WATER SHUT-OFF			
FRACTURE TREAT			
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zon		
PULL OR ALTER CASING	change on Form 9–330.		
MULTIPLE COMPLETE	그 그는 사람이 살림을 하는 것이 얼굴하면 다른		
ABANDON*	그 그는 전 사람들이 함께 함께 함께 하는 것		
(other)			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is	te all pertinent details, and give pertinent dates		
measured and true vertical depths for all markers and zones pertine	nt to this work.)*		
2/8/80			
2, 6, 60	표현 경기적 기계 실천 기계 취임 중 경설 항공합 기계		
Tenneco plans to plug and abandon the McKenz	ie B #1 well $\frac{1}{2}$ by using the $\frac{3}{2}$		
attached procedure.	<u> </u>		
	不可能性的		
	FEB 1 5 1980 F		
	ากหรือดู้เหลือดู้เคีย		
	रें हैं चिडिह से हैं है		
Subsurface Safety Valve: Manu. and Type	Set @F		
18. I hereby gertify that the foregoing is true and correct	12 20 20 10 10 10 10 10 10 10 10 10 10 10 10 10		
SIGNED (LAS MAN ANTITLE Admin. Super	visor DATE 2/8/80 = 3 2 3		
(This space for Federal or State of	fice use) APPROVED		
APPROVED BY TITLE CONDITIONS OF APPROVAL. IF ANY:	DATE		
CONDITIONS OF PRESIDENCE IN PART.	評解 134 1980 1		
1. Such	France of Sing		

MLASS MicKengie "B" MELL MO. 1 8-5/8 "On, 24 18, J-55 CCC...; 225 TOC 0 ____Surface ____. 270' ... 4-1/2 "OD, 11.6/9.5 LB, J-55 CSC.H/ 340 TOC @ 3200 ft. DETAILED PROCEDURE agecollar 370**3'** 1. MIRUSU. 2. NDWH, NUBOP. 3. POOH w/tbq. 4. PU cmt retainer & RIH to 6467'. Squeeze Dakota perfs through retainer w/100sxs Class B neat cmt. 5. POO retainer and spot 10 sx cmt on top. 6. POOH laying down all but 1900' of thg and spot the following class B neat cmt plugs: Depth Plug Zone 5520**-**595**0** 35 sx Gallup PLO . 4250-4700 30 sx 3470-377**0** CH 7. Perforate 2025' to 2026' (PC) w/4 holes. 8. Set cmt retainer @1900'. 9. Squeeze perfs w/50 sx cmt. 10. Spot 10 sx cement on top of retainer. 11. POOH laying down tubing. 12. Perforate 300'-301' w/4 holes. 13. Establish circulation and cement to surface leaving 4-1/2 full of cement. 14. NDBOP, cut off WH, install P&A marker. 15. Clean, grade & reseed location. 6509 6651 6656 67001

Perfs 4 JSPF 6509-29' 6507-78' 6633-51'