

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form 9-331
Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

SF 081298

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Williams

9. WELL NO.

1-A

10. FIELD AND POOL, OR WILDCAT

Horseshoe - Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 12, 30N, 16W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

C & S Casing Pulling Company

3. ADDRESS OF OPERATOR

Box 778, Craig, Colorado, 81625

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' from north & West

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5500 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐


ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to pull csg. plug & abandon, as follows:

1. Spot cement plg from 1800' to TD
2. Cut & pull 5½" csg. & spot 50' cement plg inside stub & 50' above stub
3. Fill hole with mud
4. place 5 sx cement plug at surface with marker
5. Clean & restore surface location



18. I hereby certify that the foregoing is true and correct

SIGNED

Robert J. Lawrence

TITLE

Partner

DATE 7/24/67

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: