

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bulletin No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF-081226

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

Horseshoe Gallup Unit

8. FARM OR LEASE NAME

Horseshoe Gallup

9. WELL NO.

236

10. FIELD AND POOL, OR WILDCAT

Horseshoe Gallup

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 3, T-30N, R-16W

12. COUNTY OR PARISH 13. STATE

San Juan

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER Injection Wells

2. NAME OF OPERATOR
ARCO Oil and Gas Company, Division of Atlantic Richfield Co.

3. ADDRESS OF OPERATOR
1816 E. Mojave, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
2310' FNL, 1640' FWL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, OR, etc.)
5557' GL

16 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ARCO Oil and Gas Company respectfully requests approval of long term shut-in status on this well. At this time, under the current waterflood operation, ARCO cannot economically operate the subject well. An ongoing study to determine the feasibility of CO₂ flooding for the Horseshoe Gallup Field is underway, which may yield significant additional oil recovery. Implementation of a CO₂ flood would require the workover of existing wells, and the drilling of new wells. For this reason, ARCO proposes that this well be maintained in the long term shut-in status so that the wellbore will be available, should it be needed as part of a future CO₂ flood. This plan eliminates the economic waste of potentially usable wellbores, and promotes conservation.

RECEIVED
BLM MAIL ROOM
87 JUL -1 PM 3:00
FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

RECEIVED
JUL 1 1987
JUL 1 1987

THIS APPROVAL EXPIRES

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Supervisor

DATE 6/30/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side
NMOCC