Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

Budget Bur	eau No.	1004-0135
Expires:	March	31, 1993

5.	Lease	Designation	and	Scrial	I

BOKEAU OF EARD MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different re Use "APPLICATION FOR PERMIT—" for such proposals	NOG 8707-1146 6. If Indian, Allottee or Tribe Name eservoir. Navajo
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well Oil X Gas Other 2. Name of Operator Harken Southwest Corporation Outside Energy 3. Address and Telephone No. P.O. Box 612007, Dallas, Texas 75261-2007 (214) 753-69 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Section 13-30N-21W 1695' FNL & 1980' FEL CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE	30-045-20165 10. Field and Pool, or Exploratory Area Wildeat Uncles Curle 11. County or Parish, State San Juan, NM
TYPE OF SUBMISSION TYPE OF	
Notice of Intent X Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated d give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	late of starting any proposed work. If well is directionally drilled,

The subject well was plugged and abandoned on November 28, 1995 as follows:

NOTE: BLM representative Ron Snow on location any deviation from original approved procedures was either approved or required by BLM rep.

RIH, sting into 7-5/8" cmt retainer @ 1571' KB - could not get into retainer, circ 60 bbls wtr and worked tbg to sting into retainer - unable to get into retainer. BLM rep directed cmt to be placed on top of retainer @ 1571' KB. Plug #1 -75 sxs - 1571' to 1232' KB (339'). Cutler top @ 1295'. Set 7-5/8" cmt retainer @ 1135' KB. Est rate into DeChelly perfs @ 3 BPM @ 900 psig. Pumped 28 sx into retainer, cmt hit perfs and press up to 1200 psig <1 BPM to squeeze DeChelly. Stung out of pkr and placed 22 sxs on top of packer. Plug #2 - 50 sxs - 1234' to 1030' KB (204'). Balanced Plug #3 - 34 sxs - 717' to 567' KB (150'), covered csg shoe @ 652'. Balanced Plug #4 - 15 sxs - 50' KB to surface. Cut csg 4' below surface and weld on regulation subsurface marker. Surface restoration and reseeding will be scheduled between July 1 and September 15, 1996 per BLM stipulations in letter dated October 18, 1995.

BECLABITO PERMANENTLY ARANDONED ON 11/28/05

CC: Navajo Nation		11120/75
BIA - Gallup		
14. I hereby certify that the foregoing is true and correct Signed	Title Production Admi	inistrator 11/29/95
(This space for Federal or State office use) Approved by	Title	Date
Conditions of approval, if any:		APPROVED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United State. or representations as to any matter within its jurisdiction.