

6 BLM 1 File
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

AUG 14 1986

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ P & A

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

P O Box 208, Farmington, NM 87499

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

790' FSL - 1850' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)
5702' GL

5. LEASE DESIGNATION AND SERIAL NO.
NM 030555A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dare Devil

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT
Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 10, T 30N, R 13W, NMPM

12. COUNTY OR PARISH
San Juan

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Request BLM Inspection

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As indicated in the approved Application for Permit to Drill, under Environmental Stipulations, Section 3: Reseeding and Abandonment - Subparagraph C: "If in the opinion of the surface management agency" (in this case the BLM), "the seeding is unsuccessful, the lessee/operator may be required to make subsequent seedings". The recommended method of seeding explained under the same Section 3, subparagraph B was performed August 29, 1986 for the No. 1 Mexico Federal "L" & the No. 1 Dare Devil locations. Surface restoration has been completed and is now ready for BLM inspection.

RECEIVED

AUG 18 1986

OIL CON. LOG

DATE

15 SEPTEMBER 1986

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan

TITLE Geologist

DATE 8-8-86

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE