Form 9-331 5 MMS, Fmn] NWPL. Randolph El Dec. 1973	Paso File Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 10561
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	<u> </u>
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME: See See See See See See See See See Se
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME 999 3
1. oil gas	Big Field 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
well well other	9. WELL NO.
2. NAME OF OPERATOR	2 9878 2 328
DUGAN PRODUCTION CORP.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	<u> Wildcat 국무하다 - 유명</u>
P O Box 208, Farmington, NM 87499	11. SEC., T., R., M를 OR BLK. AND SURVEY OR AREA : 유명 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등 등
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 3 T30N R14W
below.) AT SURFACE: 790' FNL - 1850' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan 구설등 및 NM
AT TOTAL DEPTH:	14. API NO. \ 문문주도 표 하는 2년
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15 PLEVATIONS (SHOW DF, KDB, AND WD)
OUDOSQUISMY DEDORT OF work	<u> </u>
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF TEST WATER SHUT-OFF FRACTURE TREAT	विश्वेष्टित के सिकेश्वे
TEST WATER SHUT-OFF	40 40 00 00 00 00 00 00 00 00 00 00 00 0
SHOOT OR ACIDIZE	<i>බ</i> හිට
REPAIR WELL	(NOTE: Report results of multiple completion or zone
TOLE ON METER SHOWING	THO THAT I DEST
MULTIPLE COMPLETE U U)	Control of the contro
ABANDON* XX	The state of the s
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent.)	it to this work.)* nicht en
Request permission to plug and abandon as 1. Fill 2-7/8" O.D., 6.4#, CW-55 lO rd re	follows: Smooth and a second s
1. Fill 2-7/8" O.D., 6.4#, CW-55 10 rd re	g. tubing for casing tromនៃខ្លី
PBTD 1275' to surface using 35 sx clas	s "B" neat cement ្ នំម្ចីម៉ឺង
Install permanent dry hole monument.	라는 사람들은 다른 기를 보고 있다. 10년 1년
3. Fill all pits.	6562
4. Clean well location of all equipment,	pipe, junk, and turasis as a second
5. Restore surface per surface management	agency guide ines.
6. Remove tie-downs.	
u .	FFB 1 4 1983 7 7 7 7 8 8 2 8 8 3 2
	TED 1 TO STORE THE STORE T
OII	CON. DIVISION FILE
Subsurface Safety Valve: Manu. and Type	1 DIST. 3. 3. 4. 3. 5. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
18. I hereby of thify that the foregoing is true and correct Agent	2=4-83
Sherman E. Dugan	DATE APPOVED
(This space for Federal or State of	fice use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	FEB 8/1983
S .	Ju And
<i>ا</i> لكل ا	V JAMES P. STIVIS
${f v}$	DISTRICT ENGINEER

AILLOOO