Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources

Form C-103 Revised 1-1-89

District Office OIL CONSERVATION DIVISION **DISTRICT I** WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O.Box 2088 3004523569 Santa Fe, New Mexico 87504-2088 DISTRICT II 5, Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE X STATE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Likins Gas Com A 1. Type of Well: OIL OTHER 8. Well No. 2. Name of Operator Attention Pat Archuleta 3E AMOCO PRODUCTION COMPANY 9. Pool name or Wildcat 303-830-5217 **Basin Dakota** Colorado 80201 P.O. Box 800 Denver 4. Well Location 1790 **EAST** SOUTH Line and Feet From The Line Feet From The **Unit Letter** SAN JUAN 34 30N 9W **NMPM** County Township Range Section 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice Report or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUG AND ABANDON ALTERING CASING PERFORM REMEDIAL WORK REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB X Recompletion OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Amoco Production Company requests permission to recomplete this well to the Blanco Mesaverde per the attached procedures and downhole commingle with the Basin Dakota when approval is received. If you have any technical question contact Mark Rothenberg at (303) 830-5612. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 05-01-1997 Staff Assistant _ TITLE . DATE SIGNATURE 303-830-5217 TELEPHONE NO. Pat Archuleta TYPE OR PRINT NAME

(This space for State

DRIGINAL SIGNED BY ERNIE BUSCH

DEPUTY OIL & GAS INSPECTOR, DIST. #3

MAY

APPROVED BY -CONDITIONS OF APPROVAL, IF ANY:

Hold C-104 For NSC

Likins Gas Com A 3E Orig. Comp. 10/79 TD = 7057' PBTD = 7051' Page 2 of 3

Suggested Procedure:

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Record DK SITP and CP. Blow down well. Kill with water if necessary.
- 3. Lower 2 3/8" tubing and tag for fill. POOH with 2 3/8" tbg. NDWH. NUBOP.
- 4. Set RBP at 4900' with wireline or tubing and spot sand on RBP. Circulate hole clean.
- 5. RIH with tubing and packer and Pressure test casing/plug to anticipated frac pressure. Isolate any leaks.
- 6. Run cased hole neutron log and gamma ray from RBP to 3900'. Run CBL/CCL/GR from RBP to TOC and atleast 3700'. Determine actual TOC and relay all logging info to Mark Rothenberg (continuous fax 303-830-4276) in Denver and verify if remedial cement squeezes will be needed prior to fracture treatment and to also determine perforations.
- 7. Correlating to Cased Hole Neutron Log, perf Point Lookout and Menefee select fire at depths determined from log.
- 8. RIH with tbg and packer and break down/ball off perfs with acid and 1.1 SG RCN balls. Knock off balls with packer. TOH with packer.
- 9. Frac Point Lookout and Menefee perfs according to frac procedure A.
- 10. Flow back Point Lookout and Menefee to tank as soon as possible on 1/4" choke, increasing to 1/2" or larger according to activity of well and sand or water production. Establish and record gas, water, oil rates and producing and shut in TP and Cps. Obtain water and gas samples.
- 11. RIH with tubing and scraper and tag sand, c/o sand so level is below bottom perf of second stage frac, then TOH and RIH with RBP and set at depth determined from log.
- 12. RIH with tubing and packer and pressure test casing/plug to anticipated frac pressure. Isolate any leaks.
- 13. Correlating to Cased Hole Neutron Log, perf Cliff House and Menefee select fire at depths determined from log.
- 14. RIH with tbg and packer and break down/ball off perfs with acid and 1.1 SG RCN balls. Knock off balls with packer. TOH with packer.
- 15. Frac Cliff House and Menefee perfs according to frac procedure B.
- 16. Flow back Cliff House and Menefee to tank as soon as possible on 1/4" choke, increasing to 1/2" or larger according to activity of well and sand or water production. Establish and record gas, water, oil rates and producing and shut in TP and Cps. Obtain water and gas samples.
- 17. RIH with tubing and scraper and c/o to RBP. TOH and RIH with retrieving head and retrieve RBP. TOH.

Likins Gas Com A 3E Orig. Comp. 10/79 TD = 7057' PBTD = 7051' Page 3 of 3

- 18. RIH with tubing and retrieving head and c/o to second RBP. Retrieve second RBP and TOH.
- 19. TiH with 2 3/8" production string and clean out to PBTD land at original depth of 6957' (1/2 mule shoe on bottom and a SN 1 joint off bottom). RDMOSU.
- 20. Place well on production.

NOTE: Since this procedure may involve recompletion and DRA expenditures, please be sure to label all invoices accordingly so that costs can be accounted for properly.

If problems are encountered, please contact:

Mark Rothenberg (W) (303)830-5612 (H) (303)841-8503 (P) (303)553-6448

Amoco Production Company

ENGINEERING CHART

SUBJECT LIKINS GAS COM A 3 E 3004523569

2040' FSL × 1790' FEL J34-30N-9W FEE LEASE

By MDE

3 pud 7/79	(/// 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
NO WORKOVERS	<i>ξ[</i> / ₁	1 1 1 1 TO BOT
	(-14 <u>1</u>	8 78", 24#, K-55@ 3 25 CMT N/ 240 54 Class B Neat
)	eve to sort
	>	
	/	
)	
		· ·
	/ / /	
	1/4	1 12
		5 STay 2 tool 4940'
	2	CNT 1010 18 (1253 15, 5 0/30 POZ, 6/6 Get
	\	1/2 ct/sx perlite
	PERF 2 STF 6734-6760 65,10574	
	PERF 2 STF 6734-6760 65,7554 10,225 PERF 2 SPF 6844 - 67641 17,000 to 17	238, 4,7#, J-55@ 6957' SN,SAWIT 41/2", 10,5#-11,6#, X-55@ 7051 CMT 850 58 CMS1 B, 50'50 POZ 67050, 2*/1x TV+

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 **DISTRICT II** 311 South First,, Artesia, NM 88210

API Number

DISTRICTIII 1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV 2040 South Pacheco, Sante Fe, NM 87505

3004523569

State of New Mexico Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 South Pacheco Santa Fe, New Mexico 87505 C-1417 Form C-102 Revised October 18, 1994
Submit to Appropriate District Office
State Lease - 4 Copies
Fee Lease - 3 Copies

Fred B. Kerr, Jr.

3950

Certificate No.

Blanco Mesaverde

WELL LOCATION AND ACREAGE DEDICATION PLAT

Pool Code

72319

Pool Name

	3004523	509	1	12313					
Property Code 0007	05	Property Name		Lik	Well Number 3E				
GRID No.		Operator Name			Elevation				
0007 No.	78	Operator Hame	AMOCO PRODUCTION COMPANY				5716		
				Sı	ırface Loc	ation			
UL or lot no.	Section	Township	Range	Lot. Idn	Feet from the	North/South Line	Feet from the	East/West Line	County
UNIT J	34	30N	9W		2040	SOUTH	1790	EAST	San Juan
		Bott	om Hol	e Location	ı If Differe	nt From Sur	face		
UL or lot no.	Section	Township	Range	Lot. Idn	Feet from the	North/South Line	Feet from the	East/West Line	County
edicated Acreage	e:	Joint or Infill	Cons	solidation Code	Order No.				
312.36	3								
								that the informtion co	
		OR A NO	N-STANE	DARD UNIT	HAS BEEN A	PPROVED BY	THE DIVISIO	N	
								TOR CERTIFIC	-
								te to the best of my k	
			į				veney		
							Signature	. 0	0 4 1
			:				ta	& arch	ulita
							Printed Nam	e Pat Archulet	·a
				ko.,	ner-		Position		
				* ***		v.		Staff Assista	nt
				:		37 371.	Date		
						ENERGY.		5/06/9	7
							SURVE	Y CERTIFICA	ATION
								that the well location : n field notes of actual	
						1790'	or under my sup	ervision, and that the est of my knowledge a	same is true and
								05/11/1997	7
							Date of Sur	rvey	
ł							Signature &	Seal of Profess	ional Surveyor