UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Not	ices and Reports on Wells			
1. Type of Well GAS	SEP 2 2 1994	5. 6.	SF-078	lian, All. o
2. Name of Operator MERIDIAN OIL		7.	Unit A	Agreement Nam
3. Address & Phone No. of Operat PO Box 4289, Farmington, NM 4. Location of Well, Footage, Se 905'FSL, 905'FEL, Sec.17, T-3	87499 (505) 326-9700		Quinn API We 30-045 Field Blanco County	
12. CHECK APPROPRIATE BOX TO IND Type of Submission _X_ Notice of Intent Subsequent Report Final Abandonment 13. Describe Proposed or Corola	Type of Action Abandonment Change X Recompletion New Co Plugging Back Non-Ro Casing Repair Water Altering Casing Conver	e of Pla onstruct outine F	ns ion Tracturi	-
in the Dakota. The production is seen.	Mesaverde and Dakota tubing st well through the 5 1/2" liner formation will be tested openho a 3 1/2" liner will be run and perforated and fracture stimul	to a ne	ew depth suffici	n of 8270' .ent
	nesaverue/ Dakota.		070 FARMINGTON, NM	RECEIVED BLM 94 SEP 14 PN 3: 20
Signed Stalkuld (This space for Federal or State of		Date	9/13/9	
APPROVED BY CONDITION OF APPROVAL, if any:		and the same same same) VE L
//	<u> </u>		EP 1 4'	1904