

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Grande Rd., Alameda, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30 045 23608

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Amoco Production Company Attn: John Hampton

3. Address of Operator
P.O. Box 800, Denver, Colorado 80201

4. Well Location
Unit Letter E : 1830 Feet From The North Line and 1135 Feet From The West Line
Section 25 Township 30N Range 9W NMNM San Juan County

10. Elevation (Show whether DF, RKB, RT, CR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: <u>Abandon cathodic protection well</u> ☒		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The cathodic protection well associated with the above well will be plugged and abandoned per the attached procedure.

RECEIVED

JUN 28 1990

OIL CON. DIV
DIST. 2

Please contact Cindy Burton (303)830-5119 if you have any questions.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John Hampton TITLE Sr. Staff Admin. Supr. DATE 6/26/90

TYPE OR PRINT NAME John Hampton TELEPHONE NO. 303-830-5025

(This space for State Use)

APPROVED BY Original Signed by CHARLES GIBSON DEPUTY OIL & GAS INSPECTOR, DIST. 23 DATE AUG 07 1990

CONDITIONS OF APPROVAL, IF ANY:

GROUND BED ABANDONMENT

WELL NAME: Jacques 3

LOCATION: S25-T30-R9

- 1) Weld 6 " dia. spool with diverter line to pit
- 2) MIRU
- 3) Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free. Wash hole to TD ~~ft.~~
- 4) Pump * sx of neat cement w/ 1/4 lb. sk. Flocele. Pull out work string.
- 5) Top off hole with cement, set flexible pipeline marker as PxA marker.
- 6) RDMO

Ground Bed Specifications

TD _____ ft.

Hole Dia. _____ inches.

Casing Dia. _____ inches

Casing Length _____ ft.

} UNKNOWN

* Sacks of cement = $(\text{dia})^2 \times \text{TD} \times .00693$
where dia is in inches,
TD in feet.

JAB.GRA