
Form 3160-5

UNITED STATES

FORM APPROVED					
Budget Bure	u No.	10	04-01	3:	
Expires:	March	11	1001		

	ARTMENT OF THE INTERIOR AU OF LAND MANAGEMENT	Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.
Do not use this form for proposa	OTICES AND REPORTS ON WELLS als to drill or to deepen or reentry to a different reservoir. TON FOR PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
S	7. If Unit or CA, Agreement Designation	
1. Type of Well Substitute Substitute Other	Colorado 80201 or Survey Description)	8. Well Name and No. Pritchard #10 9. API Well No. 30 045 27016 10. Field and Pool, or Exploratory Area Basin Fruitland Coal Gas 11. County or Parish, State San Juan, New Mexico
12. CHECK APPROPRIATE	E BOX(s) TO INDICATE NATURE OF NOTICE, REPO	DRT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	1
X Notice of Intent	Abandonment Recompletion	Change of Plans New Construction
Subsequent Report Final Abandonment Notice	Plugging Back Casing Repair Altering Casing	Non-Routine Fracturing Water Shut-Off Conversion to Injection
	X Other Sidetrack, Compl. Fr	uitlanskpose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give subsurface locations and measured and	early state all pertinent details, and give pertinent dates, including estimated date of starting true vertical depths for all markers and zones pertinent to this work.)*	
Amoco Production Company coal zone in the subject	y intends to sidetrack and openhole cavity	complete in Fruitland
See attached for procedu		



OIL CON. DIV.

If you have any questions please call Julie Zamora at 303-830-6003.

CT 22 MD: 29	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowing or representations as to any matter within its jurisdiction.	gly and willfully to make to	o any department or agency of the Unit	ted States any falses function or fraudulent statements
		(V) 06V	28 1991
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Title	APP	KUVEU
14. I hereby certify that the foregoing is true and correct Signed Signed	Tide <u>Sr. Sta</u>	ff Admin. Supv	BALF (21/91
			1. M.

PROCEDURE PRITCHARD A-10

- 1. Modify location for air drilling package if necessary.
- 2. MIRUSU. Blow well down. Kill if necessary w/fresh water. NDWH and NUBOP.
- 3. Pull rods and tubing.
- 4. NU 7 1/16" tubing head.
- 5. TIH with CIBP and set at 2585'.
- 6. TIH with 7" A/Z packer/whipstock assembly and starting mill.
- 7. Set packer so that bottom of the window will be at 2578' (check collar log to ensure that window is not in a collar and adjust depth in necessary).
- Shear carrier lug bolt with 40-75,000# pull.
- 9. Commence cutting window with starting mill. Mill up lug bolts and TOOH.
- 10. PU window cutting mill and watermelon mills, TIH and cut window plus 3-5' of formation.
- 11. TOOH and PU tapered mill, string and watermelon mills.
- 12. TIH and elongate window and smooth cut out any burrs left in window. Mill additional 5'.
- 13. TOH and PU a building BHA/CST BHA:

4 3/4" bladed mill
N.B. stabilizer
10 - 3 1/2" DC's with float
2 7/8" AOH drill pipe

14. Drill to TD of 3140' with expected coals at:

2835'-2844' 2890'-2903' 2928'-2938' 2951'-2963' 2972'-2980' 3019'-3034' 3057'-3073' 3117'-3136'

15. TOOH and commence openhole cavity procedure.