

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

350' FNL, 775' FWL, Sec. 4, T-30-N, R-9-W, NMMPM

D

5. Lease Number
SF-081098

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Riddle #1R

9. API Well No.
30-045-27564

10. Field and Pool
Blanco Mesaverde

11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☒ Notice of Intent

☐ Abandonment

☐ Change of Plans

☐ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☒ Other - Tubing change

13. Describe Proposed or Completed Operations

It is intended to change the tubing in the subject well according to the attached procedure and wellbore diagram.

RECEIVED
MAY 12 1997

OIL COAL DIST.
DIST. 3

070
97 MAY 12 1997

14. I hereby certify that the foregoing is true and correct.

Signed Duane W. Spencer (VGW5) Title Regulatory Administrator Date 5/5/97

(This space for Federal or State Office use)

APPROVED BY Duane W. Spencer Title _____ Date May 12 1997

CONDITION OF APPROVAL, if any:

UNMOOD

WORKOVER PROCEDURE -- TUBING REPLACEMENT

Riddle #1R
DPNO 6594A
Blanco Mesaverde
Sec. 4, T30N, R09W
San Juan County, New Mexico

1. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and BR safety regulations.
2. MOL and RU. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 1% KCl water as necessary. ND wellhead and NU BOP. Test BOP. Send wellhead to wellhead company to be inspected.
3. TOOH and LD 1-1/2" tubing (226 jts with 9 2-1/16" blast joints). If tubing is stuck, contact Operations Engineer. PU 2-7/8" tubing, TIH, and CO to PBTD.
4. Land 2-7/8" tubing at 7600'. PU 1-1/4" IJ tubing with Trico 1-1/4" jet pump bottom hole assembly and TIH. Land 1-1/4" tubing at 7600'. ND BOP and NU wellhead.
5. Rig down, move off location and restore location.

Recommended: *[Signature]* 4/27/97

Operations Engineer

Approval: *M. L. Kikpatich* 4/14/97

Drilling Superintendent

CONTACTS:

Operations Engineer

Gaye White

326-9875

Riddle #1R

350' FNL, 775' FWL, Sect. 4, T30N, R109W
 San Juan County, New Mexico
 Spud: 2/11/91
 Comp. 6/15/91

	MD	TVD
Ojo Alamo	1680'	1680'
Kirtland	1874'	1874'
Fruitland	2680'	2680'
Pictured Cliffs	3030'	3030'
Lewis	3210'	3210'
Upper Cliff House	4754'	4546'
Massive Cliff House	5314'	4770'
Menefee	5303'	4878'
Massive Point Lookout	6008'	5228'
Lower Point Lookout	6762'	5359'

