In Lieu o Form 316 (June 19	60	DEPARTM	ED STATES ENT OF INTERIOR AND MANAGEMEN	т		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993	
Do not u	SUNDR	Y NOTICE AND	REPORTS ON WELI	LS RECEIVED servoir. Use "ABALICATION	5.	Lease Designation and Serial No. SF-078765	
50	To	O DRILL" for perm	it for such proposals	98 DEC -4 PM 2:	18	If Indian, Allottee or Tribe Name	
		SUBMIT IN T	RIPLICATE	070 FARMINGTON,	NM O	If Unit or CA, Agreement Designation ROSA UNIT	
1.	Type of Well □ Oil Well ■ C	Gas Well [	☐ Other	Andrew Control of the	8.	Well Name and No. ROSA UNIT #156	
2.	Name of Operator WILLIAMS PRODUCTION	ON COMPANY	<u> </u>	REIVED	9.	API Well No. 30-045-29661	
3.	Address and Telephone N PO BOX 3102 MS 37-2,		(918) 588-4592	DEC 1 1 1998	10.	Field and Pool, or Exploratory Area BLANCO MV	
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description)  1040' FNL & 960' FEL, NE/4 NE/4 SEC 9-31N-6W  County or Parish, State SAN JUAN, NM						
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
	TYPE OF SUBMISSION TYPE OF ACTION						
	☐ Notice of Intent  ■ Subsequent Report  ☐ Final Abandonment		☐ Abandonment☐ Recompletion☐ Plugging Back☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐		<ul><li>☐ Change of Plans</li><li>☐ New Construction</li><li>☐ Non-Routine Fracturing</li></ul>		
			☐ Casing Repair☐ Altering Casing			☐ Water Shut-Off ☐ Conversion to Injection	
			■ Other <u>COMPLETION OPERATIONS</u>			☐ Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
13.	Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*						
10-20-1998 MOL and rig up. TIH with 58 joints of tubing. Rig up BJ and pressure test. Established rate of 1/2 BPM at 2600#. Liner is leaking. Continue to TIH with tubing. TOH and replace faulty BOP. SDON. Will squeeze liner top 10/20/98.							
10-21-1998 Pick up 4-1/2" packer and TIH. Set packer in liner at 3603'. Pressure test liner to 3500# - held OK. Pressured backside to 1600# with some pressure loss. TOH and changed to 7" packer. TIH and set packer at 3565'. Pressure tested 7" casing to 2000# - held OK. Pressure tested liner top and 4-1/2" casing to 3500# - held OK. Released packer and pressure tested the entire wellbore to 3500# - held OK. TOH and lay down packer. Pick up 3-7/8" bit and TIH to 3540'. Shut down until Thursday.							
10-22-1998 - 10-23-1998 Shut down							
Continued on Reversed Side							
14. I hereby certify that the foregoing is true and correct							
Signed SUSAN GRIGUHN SULLERY Title CLERK Date November 11							
(This space for Federal or State office use)							

, J. OGD FARMINGTON DISTRICT OFFI Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false fictitious or traudulent statements or representations as to any matter within its jurisdiction.

Title

Approved by

Conditions of approval, if any:

DEC 0 8 1998

# 10-24-1998

TIH and tag PBTD at 6140'. Circulate hole clean. Pressure test to 3500# - held OK. POH to 6011' and spot 500 gal. of 15% HC. TOH. Perforate Point Lookout at 5728, 31, 34, 37, 40, 43, 46, 49, 52, 55, 58, 62, 66, 69, 72, 74, 76, 90, 93, 96, 99, 5802, 05, 08, 20, 24, 33, 36, 39, 56, 60, 63, 65, 69, 70, 5901. 18, 22, 26, 30, 34, 50, 52, 54, 72, 76, 83, 92, and 96. Total of 49 (0.37") holes. Ready wellhead to frac. SDON. Roads and location are very muddy.

# 10-24-1998 - 10-26-1998

Shut down

# 10-27-1998

Bad road conditions. Had to cat equipment to location. RU BJ & pressure test lines to 4500#. Balled off Point Lookout in 1000 gal of 15% HCl and 70 ball sealers. Good ball action and complete ball off. Ran junk basket and retrieved 70 balls with 49 hits. Fraced PL with 77,000# of 20/40 sand at 1-2 ppg in 1900 bbl of slick water. Job completed at 1715 hrs. 10/27/98. ISIP = 440#, 15 min. = 0#. AIR = 100 BPM, MIR = 103 BPM, ATP = 3300#, MTP = 3450#. Set 7" CIBP at 5693". Pressure tested to 3500# - held OK. Perforate CH/MEN under pressure at 4510, 14, 18, 22, 26, 30, 34, 4680, 84, 88, 96, 4700, 04, 4838, 42, 5272, 74, 5450, 88, 91, 94, 97, 5500, 16, 19, 22, 25, 28, 31, 34, 37, 40, 94, 97, 5600, 12, 15, 18, 24, 26, 28, 53, 55, & 57. Total of 44 (0.37") holes. Ball off CH/MEN with 70 ball sealers in 1500 gal of 15% HCl. Ran junk basket and retrieved 70 balls with 35 hits. Fraced CH/MEN with 80,000# of 20/40 sand at 1-2 ppg in 1445 bbl of slick water. Job completed at 2300 hrs. 10/26/98. ISIP = 500#, 15 min = 260#. AIR = 63 BPM, MIR = 67 BPM, ATP = 2400#, MTP = 2900#. Rigged down frac crew. SDON.

### 10-28-1998

Bad road conditions. ND frac head and NU stripper rubber. Pick up 3-7/8" bit and TIH to 3476'. Unload well with drill gas. Continue blowing well with soap sweeps. Recovering heavy sand. SDON with watchman.

#### 10-29-1998

Bad road conditions. TIH and clean out 3' of fill to CIBP. Blow well with soap sweeps. Pitot test CH/MEN at 970 MCFD with a light mist. Rig up swivel and drill CIBP. Blow head off well. Push plug to 6136'. Blow well with soap sweeps. POH to 4497' and continued to blow well. SDON with watchman.

### 10-30-1998

Bad road conditions. Flow well and pitot test at 2,684 MCFD with a light mist. TOH and lay down bit. TIH with production tubing to 6126'. Tagged 10' of till. Cleaned out to PBTD and ran soap sweeps. POH to and continued to blow well. SDON with watchman.

### 10-31-1998

Bad road conditions. Pitot test at 2,830 MCFD with a heavy mist. TIH and tag fill at 6126'. Blow well with soap sweep - no sand. POH and land 193 jts (5982.43') of 2-3/8", 4.7#, J-55, EUE tubing at 5994' KB. Ran notched collar on bottom and SN on top of bottom joint at 5964' KB. ND BOP and NU wellhead. Rigged down and catted rig to Rosa #156A. FINAL REPORT.