

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**

P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**

P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.

30-039-07983

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

ENERGEN RESOURCES CORPORATION

3. Address of Operator

2198 Bloomfield Highway, Farmington, NM 87401

4. Well Location

Unit Letter N : 1105 Feet From The South Line and 1650 Feet From The West Line

Section 32 Township 32N Range 5W NMPM Rio Arriba County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
6454' GL

7. Lease Name or Unit Agreement Name

San Juan 32-5 Unit

8. Well No.

9. Pool name or Wildcat

Blanco MV

11.

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Lewis Pay Add ☒

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is intended to add the Lewis pay to this wellbore as follows:

1. MIRU. TOH.
2. Set CIBP at 5500'. Pressure test casing to 3000 psi.
3. Run GR-NEU log. Selectively perforate Lewis from 4400 - 5500' Huerfanito Bentonite top at 4300'.
4. Fracture treat with 65Q foam and 200,000# sand.
5. TIH and clean out to PBTD. Land tubing at 5800'. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Production Superintendent DATE 5/17/99

TYPE OR PRINT NAME Gary W. Brink TELEPHONE NO. 505-325-6800

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH

DEPUTY OIL & GAS INSPECTOR, DIST. 3

TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 20 1999