

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
entry side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER Re-Entry	5. LEASE DESIGNATION AND SERIAL NO. NM 29342
2. NAME OF OPERATOR Celeste C. Grynberg	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
3. ADDRESS OF OPERATOR 5000 S. Quebec St., Ste 500, Denver, CO 80237	7. UNIT AGREEMENT NAME Carraeas Canyon
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1060' FNL & 805' FWL	8. FARM OR LEASE NAME Federal (Carraeas Canyon)
9. PERMIT NO. 30-039-07991	9. WELL NO. UNIT 26 #1
10. FIELD AND POOL, OR WILDCAT Wildcat	11. SEC., T., R., W., OR BLK. AND EASEMENT OR AREA Sec 26, T32N-R5W
12. COUNTY OR PARISH Rio Arriba	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NATURE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER	☐	WATER SHUT-OFF	☐
FRACTURE TEST	☐	FRACTURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other) Re-Entry Operations	☒
(Other)	☐	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well has been previously drilled, give subsurface locations and measured and true vertical depths for all markers and rods pertinent to this work.)

4/27/90 - 4/30/90 Remove dry hole marker, build location, move-in and rig-up service unit.

5/1/90 - 5/3/90 Shut down for bad weather.

5/4/90 - 5/6/90 Finish rigging up, weld on csg extentions, drill out cmt plugs & junk to 6533' K.B.

5/7/90 - 5/9/90 Ream out tight spot in csg from 873' to 882' K.B. Run GR/CCL/CBL.

5/10/90 - 5/13/90 Repeatedly pressure test and squeeze csg holes. Holes found at 2861', 2924' & 3080' K.B. Squeezed w/ total of 150 sx class G cmt.

5/14/90 - 5/15/90 Perf 6450' K.B. w/ 4 JSPF. Cmt squeeze lower Mesa Verde. Drill out cmt.

5/16/90 Spot 100 gal 7½% HCL. Perf Mesa Verde @ 6343-45', 6348-50' & 6363-65' K.B. w/ 1 JSPF. Perf 6388-96' K.B. w/ 2 JSPF. Total of 29 holes. Acidize w/ 1000 gal 7½% HCL. Frac w/ 120,000 gal gelled water and 120,000 # 20/40 sand.

5/17/90 - 5/20/90 Swab and flow back 650 bbl water. At end water turned to black sulfur water, suspect csg leak.

5/21/90 - 5/24/90 Set pkr @ 6235 K.B., swab well. Swab mandrel stuck @ 3000' K.B. Pull tbq and clean out sand. Set pkr @ 6165 K.B. Inject 75,000 scf N₂ and flow well back.

5/25/90 Rec. 350 bbl water over night. Estimated flow rate 1 MMSCF/D gas. Flow stopped abruptly, suspect sand plug in csg or tbq. S.I. well.

18. I hereby certify that the foregoing is true and correct

SIGNED Russell A. [Signature] TITLE Manager, Reservoir Eng. DATE 10/23/90

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DEC 04 1990

*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA

BY [Signature]