Submit 3 Copies to Appropriate District Office

State of New Mexico

Form C-103

Energy, Minerals and Natural Resources Department Revised 1-1-89 OIL CONSERVATION DIVISION WELL API NO. DISTRICT I 2040 Pacheco St. P.O. Box 1980, Hobbs NM 88241-1980 <u> 30-039-07997</u> Santa Fe, NM 87505 5. Indicate Type of Lease DISTRICT II FEE X P.O. Drawer DD, Artesia, NM 88210 STATE L 6. State Oil & Gas Lease No. DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" San Juan 32-5 Unit (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: GAS WELL X óìι. WELL [OTHER 8. Well No. 2. Name of Operator 16 Taurus Exploration, U.S.A., Inc. 9. Pool name or Wildcat 3. Address of Operator Blanco Mesa Verde 2198 Bloomfield Highway; Farmington, NM 87401 4. Well Location West 790 Feet From The ___ Line South Line and _ 1850 Feet From The Unit Letter Rio Arriba County 6W 32N Range Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: **NOTICE OF INTENTION TO:** ALTERING CASING REMEDIAL WORK | X | PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS **CHANGE PLANS** TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING X OTHER: -OTHER: Pay Add 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. It is intended to add the Lewis Shale/Upper Mesaverde as follows: 1. MIRU, TOH with tubing. 2. Set CIBP @ 5350'. Run GR-CCL-CBL-Neutron Log from 4000-5300'. Selectively perforate well from 4340-5250'. Fracture treat with 700 foam and sand 4. TIH and clean out to 5800'. Land tubing at 5750'. Return to production. JUN 2 9 1993 and @ 4/561 implete to the best of my knowledge and belief. true and I hereby certify that the TITLE Production Superintendent SIGNATURE. TELEPHONE NO. (505)325-6800 TYPE OR PRINT NAME Gary Brink

DEPUTY O'L & GAS INSPECTOR, DIST. #3

DRIGINAL SIGNED BY ERNIE BUSCH

(This space for State Use)