

ILLEGIBLE

WELL

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	DATE OF NOTICE	NAME OF WELL
NOTICE OF INTENTION TO CHANGE NAME	DATE OF NOTICE	NAME OF WELL
NOTICE OF INTENTION TO TEST WATER	DATE OF NOTICE	NAME OF WELL
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	DATE OF NOTICE	NAME OF WELL
NOTICE OF INTENTION TO SHOOT OR ACROSS	DATE OF NOTICE	NAME OF WELL
NOTICE OF INTENTION TO PULL OR ALTER CABLE	DATE OF NOTICE	NAME OF WELL
NOTICE OF INTENTION TO ABANDON WELL	DATE OF NOTICE	NAME OF WELL

(Indicate above by check mark nature of report, notice, or other data)

September 2, 1950

Well No. 1 is located 1980 ft. from [S] line and 1984 ft. from [E] line of sec. 29.

Section 29

32N

5E

102

Welded

Rio Arriba

New Mexico

The elevation of the derrick floor above sea level is 6427 ft.

DETAILS OF WORK

The following plugs were placed in the hole:

48

From TD to 3200' 9.8 mud of viscosity. From 3200'-2950' cement plug. Then from 2950'-350' 9.8 mud of 48 viscosity. Then forty sacks cement from 350'-250'. 9.8 mud of 48 viscosity from 250'-25' and then 25 ft. cement up to surface. A four inch pipe of greater length than four feet was set and cemented in top of hole for permanent marker. This work was done on October 31, 1950.

RECEIVED

MAY 22 1989

OIL CON. DIST.