

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR
SCHALK DEVELOPMENT COMPANY

3. ADDRESS OF OPERATOR
P. O. BOX 25825, ALBUQUERQUE, NEW MEXICO 87125

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1055' FSL & 1190' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other)	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

--	--	--	--	--	--	--

RECEIVED

SEP 09 1987

OIL CON. DIV.
DIST. 3

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-11-87 RIG UP. NIPPLE DOWN WELLHEAD. NIPPLE UP BOP. PULL OUT OF HOLE WITH
65 STANDS. SHUT WELL IN.

8-12-87 PULL 108 JOINTS. SHUT RIG DOWN TO MAKE REPAIRS.

8-13-87 FINISH COMING OUT OF HOLE WITH TUBING AND PACKER. WENT BACK IN HOLE WITH 243 JTS. TUBING. MIX MUD. CIRCULATE HOLE. SPOT 25 SX PLUG 7810' TO 7710'. PULL 45 JTS. SHUT WELL IN.

Approved as to plan of work, and
Liability was transferred to
surface rock to be drilled.

Subsurface Safety Valve: Manu. and Type

Set @

Ft

18. I hereby certify that the foregoing is true and correct

SIGNED: Jack Crane TITLE PROD. SUPT.

DATE _____

AUGUST 21, 1987

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE _____

CONDITIONS OF APPROVAL IF ANY:

SEP 4 1987

PAGE 1 OF 2

PERMANENT RECORDS

NMOCs

*See Instructions on Reverse Side

UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR
 SCHALK DEVELOPMENT COMPANY

3. ADDRESS OF OPERATOR
 P. O. BOX 25825, ALBUQUERQUE, NEW MEXICO 87125

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
 AT SURFACE: 1055' FSL & 1190' FWL
 AT TOP PROD. INTERVAL:
 AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
 FRACTURE TREAT ☐
 SHOOT OR ACIDIZE ☐
 REPAIR WELL ☐
 PULL OR ALTER CASING ☐
 MULTIPLE COMPLETE ☐
 CHANGE ZONES ☐
 ABANDON* ☐
 (other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒

RECEIVED

SEP 09 1987

OIL CON. DIV.
 DIST. 3

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

5. LEASE
 NM 4463

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
 SCHALK 63

9. WELL NO.
 1

10. FIELD OR WILDCAT NAME
 BASIN DAKOTA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
 SEC. 34, T-32N, R-5W

12. COUNTY OR PARISH
 RIO ARRIBA

13. STATE
 NEW MEXICO

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
 6240 KB

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

(CONTINUED)

8-14-87 CIRCULATE HOLE. SPOT 25 SX PLUG 6310' TO 6210'. PULL UP TO 5424'. SPOT 25 SX PLUG 5424' TO 5324'. PULL UP TO 3080'. SPOT 25 SX PLUG 3080' TO 2875'. PULL UP TO 2512'. SPOT 25 SX PLUG 2512' TO 2300'. PULL UP TO 363' SPOT 25 SX PLUG 363' TO 263'. PULL TUBING OUT. NIPPLE DOWN BOP. CUT WELL-HEAD OFF. INSTALL P&A MARKER WITH 10 SX SURFACE PLUG.

8-17-87 RIG DOWN. RIG RELEASED.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Jack Evans TITLE PROD. SUPT. DATE AUGUST 21, 1987

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: