

F

30-039-23580

9-25-84

F. loc. 880/N; 970/W Elev. 7249 GL Spd. Comp. TD PB
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @
 Csg. Perf. Prod. Stim.

T
R
A
N
S

BO/D Grav. 1st Del. Gas
 I.P. MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS		NiTD X	Well Log	TEST DATA							
Ojo Alamo		C - 103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.	
Kirtland		C - 104	Electric Log								
Fruitland			C - 122								
Pictured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
			Acres 160								

P
o
o

WC Fr. Co. RA S 32 T 32N R 4W UD Oper. Frontier Energy Corp. Lse. Arboles 32-B No. 1

Arboles 32-B #1

D-32-32N-4W

FRONTIER ENERGY CORP.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Caller Service 4104
Farmington, New Mexico 87499

IN REPLY REFER TO
NM-28277 (WC)
3162.3-1 (016)

NOV 25 1985

CERTIFIED--RETURN RECEIPT REQUESTED


Frontier Energy Corporation
1360 Post Oak Boulevard, Suite 790
Houston, TX 77056

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 32-B Arboles, NW/4NW/4 Sec. 32, T. 32 N., R. 4 W., Rio Arriba County, New Mexico, lease NM-28277. As discussed with Mr. Robert Davant of your Company on November 19, 1985, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,


Mat Millenbach
Area Manager

Enclosure

cc:
NMOCC

RECEIVED

NOV 26 1985

OIL CON. DIV.
DIST. 3

ABANDONED LOCATION