

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
ILR	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator S & L Resources		8. Farm or Lease Name Quinlan Ranch
3. Address of Operator 1508 W. FAIRMONT, TIFFANY SQ UNIT 75604 LONGVIEW TEX.		9. Well No. 1
4. Location of Well UNIT LETTER <u>O</u> <u>1700</u> FEET FROM THE <u>E</u> LINE AND <u>1200</u> FEET FROM THE <u>S</u> LINE, SECTION <u>23</u> TOWNSHIP <u>32N</u> RANGE <u>2E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 8530' G.L. 8538' K.B.		12. County Rio Arriba

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Total Depth 2430' - Top of Dakota ss @ 2400'

- ① Ran 150' plug @ bottom of well with 30 sacks of cement
- ② Ran 150' plug across 7" casing shoe (shoe @ 500') with 30 sacks of cement
- ③ Ran 50' plug @ top of casing.

RECEIVED

AUG 15 1986

OIL CON. DIV.
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gordon H. Legg TITLE Geologist DATE 8/14/86

APPROVED BY _____ SUPERVISOR DISTRICT # _____ TITLE _____ DATE AUG 15 1986

CONDITIONS OF APPROVAL, IF ANY: