

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		7. UNIT AGREEMENT NAME Carracas Unit
2. NAME OF OPERATOR JEROME P. McHUGH		8. FARM OR LEASE NAME Carracus Unit 34 A
3. ADDRESS OF OPERATOR P O Box 809, Farmington, N.M. 87499		9. WELL NO. #5
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1850' FNL - 1190' FWL		10. FIELD AND POOL, OR WILDCAT Basin Dakota
14. PERMIT NO.		11. SEC., T., R., E., M., OR BLK. AND SURVEY OR AREA Sec. 34, T32N, R5W, NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6357' GL; 6369' KB		12. COUNTY OR PARISH Rio Arriba
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

Status

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See attached.

RECEIVED
BLM MAIL ROOM

88 MAY -5 AM 11:21

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

RECEIVED
MAY 09 1988
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

James S. Hazen

TITLE Field Supt.

DATE 5/3/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

**JEROME P. MCHUGH
P O BOX 809
FARMINGTON, N.M. 87499
505 326-7793**

**BLM SUNDRY NOTICE
CARRACUS UNIT 34A #5**

- 11-6-87 Perforated Dakota (8022' to 8085').
- 11-17-87 Frac Dakota with 40# cross-link gel and 100,000#
 20/40 sand .
 Well flowed and was swabbed to recover frac load.
 Unable to test due to formation water.
- 1-5-88 Set Bridge Plug @ 8062'KB to shut off water.
 Swabbed well without results.
- 1-15-88 Ran bottom hole pressure bomb.
- 1-22-88 Pulled bomb.
 SI due to road and weather conditions.
- 4-14-88 Checked roads and pressures.
- 4-28-88 SI casing pressure at 1635 psi; tubing 1820 psi.
 RU 0.500" choke and flowed well as follows:
 1 hr. Casing pressure 1394 psi; tubing 0 psi.
 1-1/2 hr. Casing pressure 1400 psi; tubing 0 psi.
 unloading water
 2 hr. Casing pressure 1396 psi; tubing 0 psi.
 slugging water
 SI.
- Plan to: Repair roads to location starting 5/2/88.
 RU Swabbing unit and acidize and treat
 with scale inhibitor.
 Test Dakota.