GPO 862040

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa re
Lease No.	079011
Unit	Sen Juan 32-5

SUND	RY NOTICES	AND REPORTS O	N WELLS
NOTICE OF INTENTION TO CONTICE OF INTENTION TO TO NOTICE OF INTENTION TO SENDETICE OF INTENTION TO PERSONNELS.	RILL HANGE PLANS EST WATER SHUT-OFF E-DRILL OR REPAIR WELL HOOT OR ACIDIZE JIL OR ALTER CASING BANDON WELL	SUBSEQUENT REPORT OF SHO SUBSEQUENT REPORT OF ALTI SUBSEQUENT REPORT OF RE-E SUBSEQUENT REPORT OF ABAI SUPPLEMENTARY WELL HISTOI	ER SHUT-OFF OTING OR ACIDIZING ERING CASING ORILLING OR REPAIR NDONMENT RY
	(INDICATE ABOVE BY CHECK MAR	RK NATURE OF REPORT, NOTICE, OR OTH	IER DATA)
San Juan 32-5 Un Well No. 1-23 is SW/4 Section 2 Underignated Dake	s located 790 ft. from	$m = {S \atop S}$ line and 1,350 ft.	from \(\begin{align*} \text{E} \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
(1/2 Sec. and Sec. No.)	(Ten)	(Range) (Meridian)	MP. M.
Undesignated Dok (Field) The elevation of the de	errick floor above sea le		(Seas LP Arritory)
	DETA	ILS OF WORK	Delta Control
(State names of and expected de	epths to objective sands; show si ing points, and all	zes, weights, and lengths of proposed o other important proposed work)	asings; indicate mudding jobs, ceasing-
November 5, 1960.	Spudded well at	4:00 Р. м.	Andrew Control of the State of
November 6, 1960.	of cement, 2% cal	612' MCB, set 19 joi J-55 casing at 606' w cium chloride. Circu r cement to set - res	ith 300 sacks lated to surface.
	Plata Gathering Sy	writing by the Geological Survey before the By By Beeson No.	u/au