NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional

instructions in the Rules and Regulations of the Commission. Indicate Nature of Report by Checking Below REPORT ON RESULT OF TEST OF CASING SHUT-OFF REPORT ON REPORT ON BEGINNING X REPAIRING WELL X DRILLING OPERATIONS REPORT ON REPORT ON RECOMPLETION REPORT ON RESULT (Other) OPERATION OF PLUGGING WELL Pebruary 15, 1955 Farmington, New Mexico Following is a report on the work done and the results obtained under the heading noted above at the Great western Drilling Company Pubos-State Great Western Drilling Company , Well No. 1 in the NW 4 SW 4 of Sec. 36 , The Dates of this work were as follows: Pebruary 12, 13, 15, 1955 and approval of the proposed plan (was) (was not) obtained. DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED The Pubco-State #1 was spudded @ 2:30 P. M. Eebruary 12, 1955. 193' - 10-3/4" 8rd the 32.75# casing was set @ 205' w/207 sacks @ 5:00P. M. February 13, 1955. The cement circulated. After 36 hours, the casing was pressured with 500 pmi for 30 minutes. test was satisfactory so drilling was resumed. OIL CO.4. COM DIST, 3 stern Drilling Company Div. Prod. Supt. Witnessed by......Jack Page ORIGINAL SIGNED BY I hereby certify that the information given above is true and complete Approved: OIL CONSERVATION COMMISSION to the best of my knowledge. Name..... Position......Division Prod. Superintendent PETROLEUM ENGINEER DIST. NO. 3FEB 2 5 1955 Representing.... Great Western Drilling Company

Address...Box 608, Farmington, New Mexico

	OIL	_ CONSERVA	TION COMP	HSSION		
	\$	AUTEO DE	774.37 (2.7.7	7.5		
	lic	Conies Rati	ived 4			
			1			
		Begin form of the section of the se			·	••
			·			
		·	7		•	
,						

.

•