Form 3160-5. (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED			
Budget Bureau No.	1004-0135		
Expires: March	31, 1993		

BUREA	J OF LAND MANAGEMENT	Expires: Marc	h 31, 1993
SUNDRY NO	TICES AND REPORTS ON WELLS	5. Lease Designation and Serial I	
	osals to drill or to deepen or reentry to a different reservoir.	SF-078 6. If Indian, Allottee or Tribe Na	
Use APPLICA	ATION FOR PERMIT - Tor such proposates		
	ورواق مردور المراجع ال	7. If Unit or CA, Agreement De	esignation
· · · · · · · · · · · · · · · · · · ·		_	
1. Type of Well Oli Gas Well Other		8. Well Name and No.	
2. Name of Operator	Attention:	Heaton Com A LS	\$ #13
Amoco Production Company	Gail M. Jefferson, Rm 1942	9. API Well No.	
Address and Telephone No. P.O. Box 800, Denver, Colorado	80201 (303) 830-6157	300451	
4. Location of Well (Footage, Sec., T., R., M., or		Aztec Pictu	
		11. County or Parish, State	
1750FSL 1650FEL	Sec. 32 T 31N R 11W Unit J	San Juan	New Mexico
CHECK APPROPRI	ATE BOX(s) TO INDICATE NATURE OF NOTICE, F		
TYPE OF SUBMISSION	TYPE OF ACTION	ter one, on orner	DATA
Notice of Intent	Abandonment	Change of Plans	
	Recompletion Plugging Back	New Construction Non-Routine Fracturing	
Subsequent Report	Casing Repair	Water Shut-Off	
Final Abandonment Notice	Altering Casing Other	Conversion to Injection Dispose Water	
		ort results of multiple completion or ion Report and Log form.)	n Well Completion or
	Clearly state all pertinent details, and give pertinent dates, including estimated date of starting	ng any proposed work . If well is di	rectionally drilled, give
	vertical depthe for all markers and zones pertinent to this work.)* requested permission to repair the Bradenhead leak on the ab	ove referenceded well :	and the RIM
granted approval of same Jan	uary 9, 1995. Amoco has now decided the Bradenhead repa and abandon the well per the attached procedures.		
Marian have any tankainal ava	ations along all Kharb VI. at (202) 920 4020 as assent for		
if you have any technical que	stions please call. Khanh Vu at (303) 830-4920 or myself fo	r any administrative cor	ncerns.
	men mus.	to the transfer of the second	,
			•
	D =	7 	
	(D) (E	ice wan	
	In(=		
	D ti	MAY 1 7 1985 🙂	
	மை	COM DES	
		COM. DIV.	
		Diei. 3	
14.1 hereby certify that the foregoing is true and c	Title Sr. Admin. Sta	aff Asst. Date	05-08-1995
(This space for Federal or State office use)	70		
Approved by	Title	Date	
Conditions of approval, if any:		APPRO	VED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States-any false, false

representations as to any matter within its jurisdiction.

DISTRICT MANAGER

Heaton Com A LS #13 Orig. Comp. 5/57 TD= 2380', PBTD = 2320' Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 1 1/4" tbg.. RIH with 2 3/8" workstring and cement retainer. Set retainer at 2220'. Test casing integrity to 500#. Squeeze perfs at 2270' to 2310' with 34cuft of cement. Pull out of retainer and spot cement plug to 1837' with 60 cuft cement.
- 4. RIH with perf gun and shoot squeeze holes at 856'. Attempt to circulate to surface with die water. If unable to circulate RIH with cement retainer, set 50' above squeeze holes and and squeeze perfs at 856' with 34 cuft cement. Pull out of retainer and fill hole to 200' with 63 cuft cement. Rih with perf gun shoot squeeze holes at 200' and circulate to surface with 70 cuft cement. Fill hole to surface with 34 cuft cement.
- 5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

HEATON COM A LS 013 1375 Location — 32J—31N—11W SINGLE PC Orig.Completion — 5/57 Last File Update — 1/89 by DDM

