5. LEASE

14-20-0001-8200

6. IF INDIAM, ALLOTTEE OR TRIBE NAME

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Navyje - Ute Mtn.	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME Horseshoe Gallup Unit	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	
1 oil gas —	Horseshoe Gallup Unit"#"	
well well other Injection	9. WELL NO.	
2. NAME OF OPERATOR ARCO Oil and Gas Co., a	207	
Div. of Atlantic Richfield Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR 707 - 17th Street,	Horseshoe Gallup	
P.O. Box 5540, Denver, Colo. 80217	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 35-31N-16W	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)		
AT SURFACE: Unit J,1980'FSL & 1980'FEL, Sec. 35	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL:	San Juan New Mexico	
AT TOTAL DEPTH:	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	None 15. ELEVATIONS (SHEWE, YAND WD) 5526' OH AND GAS OPERATIONS	
REPORT, OR OTHER DATA		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF	SEP 23 1982	
SHOOT OR ACIDIZE	0 E 1	
REPAIR WELL	(NOTE: Report results of multiple completion or zone	
PULL OR ALTER CASING AND THE COMPLETE	GRAND JUNCTION, COLORADO	
MULTIPLE COMPLETE		
ABANDON*		
(other) X - Set Cement Plug		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent	irectionally drilled, give subsurface locations and	
ARCO hereby asks permission to set a centinterval (1466-1496.5') in the subject with the requirements as set forth in a 1981, and a subsequent letter of April 2 of New Mexico, Energy and Minerals Depart Division (copies attached.)	well. This is in compliance memorandum dated September 30 26, 1982, both from the State	
Attached is the procedure for setting	cement plug.	
- SEP 3 0 198	SEREINEU	
COM COM COM	1. I W COD 1 0 1000	
DIST. 3	SEP 1 6 1982	
Subsurface Safety Valve: Manu. and Type	Set @ Ft. MINERALS MANAGEMENT SETTING PURANCO CO	
18. I hereby certify that the foregoing is true and correct	DURANGO, CO	
SIGNED SIEPLEN FOSE TITLE DIST. Prod. S	-	
Original Signed - Scott L. Thespace for Federal or State of	fice use) E 2 4 1982 SOT DATE	
CONDITIONS OF APPROVAL IF ANY:		
ATTACHED		

HORSESHOE GALLUP UNIT INJECTION WELLS

PLUGGING PROCEDURE

- 1. MIRU.
- 2. Release packer and pull tubing and packer out of hole.
- 3. RIH with tubing open-ended to 40' above the top perforation and pump sufficient cement to set a 100' plug inside the casing (Using light-weight cement).
- 4. POH, RD, and move off.





STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

BRUCE KING SOVERNOR ARRY KEHOE SECRETARY

April 26, 1982

POST OFFICE BOX 2088
STATE LAND OFFICE BUILDING
SANTA FE. NEW MEXICO 87501
(505) 827-2434

RECEIVED

APR 30 1982

ENGINEERING

Arco Oil & Gas Company P.O. Box 5540 Denver, Colorado 80217

ATTENTION: J. G. Bradshaw

RE: Exception to Rule 705-A for Injection Wells in the Horseshoe Gallup Unit, Federal Lease No. 14-08-0001-8200, San Juan County,

New Mexico.

Dear Sir:

Pursuant to your letter of February 18, 1982, requesting exception to Rule 705-A for fifty-seven (57) wells as listed on Table I, the Oil Conservation Division hereby denies both of your requests. You are hereby requested to take prompt action as outlined in the September 30, 1981, Memorandum. (Copy enclosed).

The Oil Conservation Division will not grant an exception to Rule 705-A if a well will not be placed in service within 6 months of the request. For future reference, supportive data for exception to Rule 705-A should include:

- 1. Proof of mechanical integrity, such as bradenhead tests, tracer logs, or other supportive tests or data.
- 2. All related OCD Division Order Numbers or Case Hearing Numbers.
- 3. A schematic of the present injection well including cement tops and quantities thereof.
- 4. Date each well was shut-in.

If you have any questions regarding this matter, please do not hesitate to contact me at (505) 827-2533.

Sincerely,

JÓE D. RAMEY

Division Director

TABLE I

Horeshoe Gallup Unit Federal Lease No. 14-08-001-8200 San Juan County, New Mexico.

List of Wells

1.	No.	26	B
----	-----	----	---

2. No. 29 B

3. No. 103 A

4. No. 105 A

5. No. 113 A

6. No. 126 C

7. No. 130 C

8. No. 132 C

9. No. 135 C

10. No. 137 C

11. No. 139 C

12. No. 141 C

13. No. 143 D

14. No. 145 D

15. No. 148 D

16. No. 150 D

17. No. 152 D

18. No. 154 D

19. No. 156 D

20. No. 160.

21. No. 215 D

22. No. 162

23. No. 164 D

24. No. 169 D

25. No. 171 D

26. No. 173

27. No. 175 D

28. No. 180)

29. No. 182 D

30. No. 184 D

31. No. 186

-32. No. 192

33. No. 194 D

34. No. 196 D

35. No. 201

36. No. 203 D

37. No. 205 D

38. No. 207 🕀

39. No. 213 📮

40. No. 217 [

41. No. 223 D

42. No. 225 D

43. No. 227 D

44. No. 229

45. No. 238

46. No. 240 D

47. No. 248 D

48. No. 250 D

49. No. 259 D

50. No. 261 C

51. No. 263

52. No. 269 C

53. No. 274 C

54. No. 275 C

55. No. 73 A

** =

56. No. 199

57. No. 211

SEP 30 1982 OIL CON COM. DIST. 3

OIL CONSERVATION DIVISION



BRUCE KING SOVERNOR LARRY KEHOE -SECRETARY POST OFFICE BOX 20 STATE LAND OFFICE BU SANTA FE, NEW MEXICO: (505) 827-2434

MEMORANDUM

TO:

ALL NEW MEXICO INJECTION WELL OPERATORS

FROM:

JOE D. RAMEY, DIRECTOR

SUBJECT:

TEMPORARY ABANDONMENT OF INJECTION WELLS

Division Rule 705A provides in part that "no injection well may be temporarily abandoned for more than six months unless the injection interval has been isolated by use of cement or a bridge plug." The Division Director may delay the cement or bridge plug requirement upon a request by the operator and a showing that such well is mechanically sound, that there is a continuing need for the well, and that the well constitutes no threat to underground sources of drinking water.

Division survey programs have found several hundred injection wells which have not been used for at least six months and which do not have the requisite plugs. Based upon these surveys the Division will be moving to enforce Rule 705A in the near future.

Operators should review the status of their injection wells and within the next six months take one of the following actions relative to injection wells which have been shut in for six months or longer:

- (1) Return the well to active operation.
- (2) Plug and abandon the well or place a <u>cement</u> or bridge plug above the injection interval.
- (3) File a workover or plugging plan and schedule with the appropriate Division district office.
- (4) File a request for exception to Rule 705A with the Division Director in Santa Fe.

September 30, 1981 fd/

CONDITIONS FOR APPROVAL

- 1. Plug to be tagged or pressure tested to 1000 psi.
- 2. Casing at the surface shall be secured with a valve or cap.
- 3. Approval effective for one year only.