## OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

August 3, 1961

Adobe 011 Company 1223 Petroleum Life Building Midland, Texas

> Ret Adobe Oil Company #1 Parker 83-31N-13W

Centlement

A: recent field inspection of the above location by Commission personnel revealed the following violations of the New Mexico Oil Conservation Commission rules and regulations:

- I. There was no well sign showing the operator and location of the well.
- 2. The tank on the lease did not have a fire wall constructed, as required by our rules.
- 3. The reserve mud pit at the location was left uncovered.

It is requested that you take immediate steps to comply with the above requirements.

Yours very truly

Emery C. Arnold Supervisor, District #3

BCA : ks

cc: Oil Conservation Commission Santa Fe, New Mexico

## DIL CONSERVATION COMMISSION

FEGG RIG BRAZOS ROAD AZTEG, NEW MEXICO

in e 141 Temporaj 1921 - Amerikans I. ja indilografi 1921 - Johann

ারকেশ্বর্গনী ই সংগ্রেম সংগ্রেম ভর্ম**ের** বিভিন্ন শ্রেম

and the second

ම උප**ිළුහන** වූ පැද්ත විශාවුකාණය වීම පදවූ මහින පාරක්ෂක වෙන්නේ මහිපියි. මෙම අමුම්පති නීතිණ අපිවූම්පති කිළි සහ ස්වූත්ත නොකරු නිනිත මහා ස්තිය මහිප මහිපියි. මේ සිට කිසිස<mark>හේ සම්බන</mark> වේ සහ ස්තියේ නිවේදීමට මහා කිසිසම මහා ක්රීඩුවේවා පරාත්

- In **Physics** with mode will a great Aparthy the equate the literature for the english of the english
- នាំ នៅតែថា បង្ហាន ខាង គេសេខ និយាស នៅថា សនាជា នៃយោស ។ ប្រទេស នេះនៃ សលាសាការមានជំនាន » ប្រជាពេញបានខេស បន្ទាប់ ការសេខនៈ

ារី វ័យ ខ**មន្តាយបស់សនី តំណែង** ក្រុយ **ខំ**បស់ន*ិសាសមាក់ លើម នេខែស្រែង ម*ុំក្រុម ក្រុម ក្រុម សំណាក់**នៃ សំណ**ស់ **លើ** ការស្រស់កាស់ការសាស

Elas Carro sact

assection of association of the second of the contract of the

- "

.54 - 51 Convertation Country on a nata Zee West Co