

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. 14-08-0001-8200
2. NAME OF OPERATOR Atlantic Richfield Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo-Ute Mtn.
3. ADDRESS OF OPERATOR 1860 Lincoln Street, Suite 501, Denver, Colorado 80203		7. UNIT AGREEMENT NAME Horseshoe Gallup Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  Unit G, 1590' FNL & 1650' FEL, Sec. 25-31N-17W		8. FARM OR LEASE NAME Horseshoe Gallup
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5807' GR	9. WELL NO. 120
		10. FIELD AND POOL, OR WILDCAT Horseshoe Gallup - Gallup
		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 25-31N-17W
		12. COUNTY OR PARISH San Juan
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☐

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was shut-in during June, 1970 because of low production making it uneconomical to operate (approximately 1 BO & 45-50 BWPD).

This well is in a large unit which is now under waterflood operations. Future plans are to conduct waterflood and tertiary recovery studies. These studies may result in a revised waterflood plan or in a tertiary recovery program that may require the use of this well in order to recover the maximum amount of oil from this reservoir.

U.S.G.S. approval to shut-in well June 27, 1970.

Two (2) copies sent to New Mexico Oil Conservation Commission

18. I hereby certify that the foregoing is true and correct

SIGNED W. A. Walther, Jr.

TITLE Dist. Prod. & Drlg. Supt.

DATE 10-18-74

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_