NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

(Form C-104) Revised 7/1/57

REQUEST FOR *** (GAS) ALLOWABLE

New Well

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well. Form C-104 is to be submitted in QUADRUPLICATE to the same District Office to which Form C-101 was sent. The allowable will be assigned effective 7:00 A.M. on date of completion or recompletion, provided this form is filed during calendar month of completion or recompletion. The completion date shall be that date in the case of an oil well when new oil is delivered into the stock tanks. Gas must be reported on 15.025 psia at 60° Fahrenheit.

Axtoc	Company or	Operator)		Michaeleo (Leae)		6	, in		1/41/
I	, S	ес ЯЯ	, T 30.11	, R. 199	, NMPM.,		lanco)	barverda	Po-
2	en Just		County. Dat	e Spudded	¥/16/60	Date	Drilling (Completed	5/14/60
		e location:	Flounties		Tota				
T	C	BA	Top Oil/Gas F	Pay 1938	Name	of Prod.	Form.	Hestry	erde
۱ ۲	١	BA	PRODUCING INT	ERVAL -				•	
			Perforations	Love .	5000				
E	F	G H	1	• • • • • • • • • • • • • • • • • • • •	Depth Casir	n ng Shoe	7293	Depth Tubing	4880
			OIL WELL TEST		,				
L	K	JI		•	bbl - of l	L .L.) - · · · · · · · · · · · · · · · · ·		Chok
		x	1		bbls.oil,				
м	N () P	1		e Treatment (afte				Choka
			load oil used	l):b	bls,oil,	bbls w	ater in	hrs,	min. Size
		<u></u>	GAS WELL TEST	· •					
			Natural Prod.	Test:	MCF/I	Day; Hour	s flowed	Choke	Size
bing ,C	asing and C	ementing Reco	ord Method of Tes	sting (pitot,	back pressure, et	tc.):	· · · · · · · · · · · · · · · · · · ·		
bing ,Co Size	asing and C Feet	ementing Reco							
Size	Feet	Sax	Test After Ac	id or Fractur	back pressure, et	2-3772	MCF		
Size	Feet		Test After Ac	id or Fractur	back pressure, et e Treatment: Af of Testing:	8-3772 Ack per	MCF	/Day; Hours	flowed 3
Size	Feet	SAX 200	Test After Ac	Method	back pressure, et e Treatment: AG of Testing:	materia.	MCF	Ch as acid,	flowed water, oil, and
Size 10 3/	7 309 7293	200 3 600	Test After Ac Choke Size Acid or Fract sand):	Method Tubing	back pressure, et e Treatment: of Testing: (Give amounts of	materia.	MCF	ch as acid,	flowed water, oil, and
Size 10 3/	7 309 7293	200 3 600	Test After Ac Choke Size Acid or Fract sand):	Method Tubing	back pressure, et e Treatment: AG of Testing:	materia.	MCF	ch as acid,	flowed water, oil, and
Suze 10 3/7 7 3/8	729;	200 3 600	Test After Ac Choke Size Acid or Fract sand): Casing Press.	Method Tubing	e Treatment: of Testing: (Give amounts of Date first oil run to	materia.	MCF	ch as acid,	flowed water, oil, and
Sure 10 3/7 7 3/8	729;	200 3 600	Choke Size Acid or Fract sand): Casing Press. Oil Transport	Method ure Treatment Tubing Press.	e Treatment: of Testing: (Give amounts of Date first oil run to	materia.	MCF	ch as acid,	flowed water, oil, and
Suc 10 3/ 7 2 3/8	729;	200 3 600	Choke Size Acid or Fract sand): Casing Press. Oil Transport	Method ure Treatment Tubing Press.	e Treatment: of Testing: (Give amounts of Date first oil run to	materia.	MCF	ch as acid,	water, oil, and
Suc 20 3/ 7 2 3/8	729;	200 3 600	Choke Size Acid or Fract sand): Casing Press. Oil Transport	Method ure Treatment Tubing Press.	e Treatment: of Testing: (Give amounts of Date first oil run to	materia.	MCF	ch as acid,	water, oil, and
Sur 10 3/ 7 2 3/8 2 3/8	729;	200 3 600	Choke Size Acid or Fract sand): Casing Press. Oil Transport	Method ure Treatment Tubing Press.	e Treatment: of Testing: (Give amounts of Date first oil run to	materia.	MCF	ch as acid,	water, oil, and
Size 10 3/7 2 3/8 2 3/8 marks:	7293 7293 4680	800 3 600	Choke Size Acid or Fract sand): Casing Press. Oil Transport	Method ure Treatment Tubing Press.	back pressure, et e Treatment: of Testing: (Give amounts of Date first oil run to	materia.	MCF	ch as acid,	water, oil, and
Size 10 3/7 2 3/8 2 3/8 marks:	7293 7293 7243 4890	Sax 800 600 that the inf	Test After Ac Choke Size Ac d or Fract sand): Casing Press. Oil Transport Gas Transport	Method Tubing Press. er er above is true	back pressure, et e Treatment: of Testing: (Give amounts of Date first oil run to	materia. new tanks the best	s used, su	ch as acid,	water, oil, and
Size 10 3/7 2 3/8 2 3/8 marks:	7293 7293 4880 eby certify	Sax 200 3 600 4 that the inf	Test After Ac Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport	Method Tubing Press. er er above is true 60, 19.50	back pressure, et e Treatment: of Testing: (Give amounts of Date first oil run to and complete to	materia. new tanks the best	of my knownpany or	ch as acid, wledge.	water, oil, and
Size 10 3/7 2 3/8 2 3/8 marks:	7293 7293 7294 4690 eby certify	SAX 200 3 600 4 5 4 6 that the inf	Test After Ac Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport Ormation given a JUN 2 4 19	Method ure Treatment Tubing Press. er er dabove is true 60, 19.60	of Testing: (Give amounts of Date first oil run to and complete to By: CRIGINAL	materia. new tanks the best (Cc.	of my knownpany or	ch as acid, ch as acid, wledge. perator)	water, oil, and
Sure 7 2 3/8 2 3/8 narks:	7293 7293 7294 4690 eby certify	SAX 200 3 600 4 that the inf ERVATION	Choke Size Acid or Fract sand): Casing Press. Oil Transport Gas Transport ormation given a JUN 2 4 19	Method ure Treatment Tubing Press. er er dabove is true 60, 19.60	of Testing: (Give amounts of Date first oil run to and complete to By: CRIGINAL	materia. for one materia. new tanks the best Co. SIGNEI	of my known or Congress of Con	ch as acid, ch as acid, wledge. perator)	water, oil, and

Address Drawer # 570, Paradington, New Musico

en de la composition La composition de la

 $\mathcal{F}_{i,j}(\mathcal{F}_{i,j}) = \frac{1}{2\pi} \left(\frac{1$

STATE OF ME TOWN COMMANSSION

TO CO STRUCT OFFICE

STATE OF ME TOWN COMMANSSION

TO CO STRUCT OFFICE

STATE OF ME TOWN COMMANSSION

TO CO STRUCT OFFICE

STATE OF ME TOWN COMMANSSION

TO COMMANSSION

TO STATE OF ME TOWN COMMANSSION

TO STATE OF TOWN COMMANSSION

TO

STATE OF NEW MEYICO

and the second of the second o