Budget Bureau No. 1004-0135 Form 3,60-5 UNITED STATES

BUBMIT IN TRIPLICATES

Other instructions on reverse side) Expires August 31, 1985 (November 1983) (Formerly 9-331) 5. LEASE DESIGNATION AND SERIAL NO. BUREAU OF LAND MANAGEMENT 14-20-603-2034 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use "APPLICATION FOR PERMIT—" for such proposals.) Navajo 7. UNIT AGREEMENT NA OTHER XX Water Supply Well WELL NAME OF OPERATOR 8. FARM OR LEASE NAME Solar Petroleum, Inc. Navajo Tribe of Indians ADDRESS OF OPERATOR 9. WELL NO. Suite 2900, 1099-18th Street, Denver, CO 80202-1999 1 (WSW) LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT At surface Horseshoe Gallup 990'fNL & 990'fWL 11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Section 10-31N-17W 14. PERMIT NO 15. BLEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISE | 13. STATE 5258' DF San Juan NM 16 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF : TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL MULTIPLE COMPLETE PRACTURE TREAT FRACTURE TREATMENT ALTERING CASING SHOUL OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT® REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17 DESCRIES PROPOSED OR COMPLETE: OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and gones pertinent to this work.) This is to request permission to extend the shut in period for the captioned well for six months. The well went down March 12, 1988. Under current market conditions, the well is uneconomical to pull and repair but it is felt that conditions may improve enough within that period to justify repairing the submersible pump and increasing water injection within the field. Previous sundry notices were filed incorrectly using the Navajo Tribe of Indians "F" #101 water injection well location and name. A correction to request deletion of those notices is attached herewith. THIS APPROVAL EXPIR 18. I hereby certify that the foregoing is true and correct 7/25/88 Stephanie L. Huntington (This space for Federal or State office use) TITLE APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse