



TONEY ANAYA
GOVERNOR

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

October 14, 1983

Mr. James Smith
Southland Royalty Company
Drawer 570
Farmington NM 87499

Re: Patterson A Com #1, O-2-31N-12W

Dear Smitty:

The attached packer test for the referenced well was inconclusive in proving zone separation.

Please reschedule and retest this well in such a manner as to prove zone separation. I suggest you shut in both zones for a minimum of three days. Blow the higher pressured zone to the atmosphere for as long as it takes to get a significant pressure drop.

Please advise this office at least 24 hours prior to the test so we may provide a witness.

If you have any questions, please contact this office.

Yours truly,

A handwritten signature in cursive script, reading "Charles Gholson".

Charles Gholson
Deputy Oil and Gas Inspector

CG/lh

cc: Well File ✓