

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW

2. NAME OF OPERATOR

BHP Petroleum (Americas), Inc.

3. ADDRESS OF OPERATOR

P.O. Box 3280, Casper, Wyoming 82602

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface 660' FSL & 660' FEL

RECEIVED

JAN 23 1986

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

GL - 5286'

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-65

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo 'U'

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo 'U'

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Horseshoe Gallup

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Section 5, T31N-R17W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☒  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐  
☐

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

BHP Petroleum (Americas), Inc. proposes to repair shallow holes in the casing of the subject well as follows:

1. ND wellhead. NU BOP. Release packer. TOOH.
2. TIH w/cement retainer and set @ + 990'. Pressure test cement retainer by injecting down tubing. Inject into perfs overnight.
3. Sting out of cement retainer. Mix and pump Class "B" cement until cement circulates to the surface.
4. Displace cement in tubing with water. Sting back into cement retainer.
5. Clean out any residual cement in tubing by backflowing well.
6. Return well to injection.

NMOCD is requiring this well to be repaired by 1-31-86; therefore, your prompt consideration of this matter will be greatly appreciated. The NMOCD has been consulted and approve of the above procedure.

RECEIVED  
JAN 28 1986  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Paul C. Bertoglio  
Paul C. Bertoglio

TITLE

Petroleum Engineer

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE 1-10-86

APPROVED

JAN 24 1986

M. MILLENBACH  
AREA MANAGER

\*See Instructions on Reverse Side