Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BURGALL OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUREA	O OF LAND MANAGEMENT	1
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals		5. Lease Designation and Serial No.
		NM-010989
		6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
I. Type of Well Oil Well Gas Well Other Attention:		8. Well Name and No. Fields A #4
2. Name of Operator Amoco Production Compa		9. API Well No.
3. Address and Telephone No.		30 045 11267
P.O. Box 800, Denver, Colorado 80201		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Blanco Mesaverde
		11. County or Parish, State
1488' FNL, 1496' FEL	, Sec. 28, T32N-R11W	San Juan, New Mexico
12. CHECK APPROPR	IATE BOX(s) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water ort results of multiple completion on Well Completion or on Report and Log form.
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.]* Amoco Production Company intends to plug and abandon the Mesaverde formation in the		
subject well. See at		RECEIVANT STEB-1, AM
	See Procedur	

14. I hereby certify that the foregoing is true and correct

Signed fully Area Title

Sr. Staff Assistant

APPROVED

Approved by

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficticlous contractions as to any matter within its jurisdiction.

PXA Procedures (Partial) Fields A 4

- 1. Record FTP, SICP, SIBHP
- 2. MIRUSU
- 3. Blow down well
- 4. Install BOP
- 5. TOH w/2 3/8" tubing
- 6. TIH with cement retainer and set @4680'.
- Pump 250 sacks of cement through the retainer to plug off the open hole. Open hole volume calculated to be 30 bbl.
- 8. Sting out and leave a 50' plug of cement on top of retainer.
- 9. TOH W/ and lay down thg.
- 10. Install wellhead.
- 11. RDSU

FIELDS A 004 Location — 28G—32N—11W SINGLE MV Orig.Completion — 11/54 LAST FILE UPDATE — 1/93 BY CSW

